



# 2013 Ponds Certifications

City of Kenosha, Wisconsin

July 9, 2014





## **EXECUTIVE SUMMARY**

Clark Dietz, Inc. evaluated the condition of 56 ponds selected by the City of Kenosha. 22 of the ponds are owned and maintained by the City, while the rest are owned privately, but have maintenance agreements with the City for functional maintenance only (not aesthetic). Clark Dietz performed a topographic survey and inspection of each of the ponds, including water and sediment depth measurements. Items such as vegetation growth, inlet and outlet condition, and potential maintenance concerns were noted. This information was then used to prepare a certification report for each of the ponds. Each report includes pond age and design data, a summary of the field findings, recommendations for pond improvements, a layout drawing of the pond and the associated structures, pictures, and the original field notes.

Tables showing the maintenance work required at each pond were prepared and are included with this report. The tables indicate the type of maintenance required, such as vegetation removal, repair of structures, or dredging. Cost estimates were developed for each of the improvements. Each pond was assigned a rank of High, Medium, or Low priority based on the maintenance required. High-priority items are those that present a danger to residents or those that are impeding the function of the pond. Medium-priority items will eventually affect the operation of the pond. Low-priority items are typically minor and/or aesthetic in nature. Two ponds were identified as not requiring any maintenance at this time.

The ponds in the High, Medium, and Low categories were then ranked in the order that improvements should be performed. The maintenance tables are further divided between City-maintained and privately-maintained ponds, but the ponds in each category were prioritized together. Dredging is currently needed at eleven ponds, and five more should be monitored over the next five years. It is recommended that dredging be performed concurrently at several ponds, especially if they are small in size, in order to limit construction costs.

The total cost of all pond improvements was calculated. A schedule of completion was developed based on annual budgets (CIP and/or operational budgets) of \$100,000, \$200,000, and \$300,000. It was assumed that 50% of the annual budget will go toward High-priority improvements, 40% to Medium-priority improvements, and 10% to Low-priority items. The years to completion for each priority category should be added together to obtain the total time to completion for that category. The City can use the schedules to incorporate the pond maintenance projects into the annual budget.

### Report Structure

All the pond certification reports are contained in one large binder. The priority ranking tables are included in the front of the binder. The binder is divided into two main sections. The section containing the reports for all the ponds maintained by the City of Kenosha is first, followed by the section containing all the ponds with maintenance agreements. Each of those two sections is divided into four subsections. The subsections are arranged starting with the High-priority improvements and step down in priority ranking to the No-maintenance ponds. The reports in the subsections are also arranged starting with the highest-priority ponds and going down to the lower-priority ponds with that same ranking. The priority ranking tables are included in each subsection.

**2014 KENOSHA POND MAINTENANCE REQUIREMENTS  
CITY OWNED/MAINTAINED**

#	POND NAME	3 acres or more?	WET/ DRY	DREDGING?	INLET/OUTLET IMPROVEMENTS?	VEGETATION REMOVAL?	REHABILITATION NEEDED	ESTIMATED COST	ENGINEERING & ADMINISTRATION	CONTINGENCIES	TOTAL COST FOR EACH POND	WORK PRIORITY	PRIORITY RANKING	TOTAL COST OF PROJECTS BY PRIORITY	YEARS TO COMPLETION WITH \$100,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$200,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$300,000 ANNUAL BUDGET <sup>1</sup>
34	Lincoln Park	Yes	Wet	Yes	Yes	Yes	Dredge to remove sediment. Clear vegetation from north end and inlet. Replace outlet structure.	\$247,000 \$5,000 \$10,000	\$31,440	\$44,016	\$337,456	High	1	\$516,488	10.3	5.2	3.4
24	Kenosha Industrial Park	Yes	Dry	Yes		Yes	Dredge to original design elevations to restore function. Clear vegetation within and surrounding pond.	\$103,000 \$5,000	\$12,960	\$18,144	\$139,104	High	2				
21	Bullen	Yes	Dry		Yes		Remove clog from outlet. Clean flow channel. Clean sediment from outlet structure.	\$2,000 \$2,000 \$2,000	\$720	\$1,008	\$7,728	High	5				
26	Whitecaps E	Yes	Dry	Yes	Yes	Yes	Dredge siltation basin. Clean 8" pipe and concrete gutters. Remove vegetation from structures. Install grate on upper outlet.	\$17,000 \$5,000 \$2,000 \$1,000	\$3,000	\$4,200	\$32,200	High	6				

NOTES:

1. Assumes 50% of budget to high-priority projects, 40% to medium-priority projects, and 10% to low-priority projects.

**2014 KENOSHA POND MAINTENANCE REQUIREMENTS  
CITY OWNED/MAINTAINED**

#	POND NAME	3 acres or more?	WET/DRY	DREDGING?	INLET/OUTLET IMPROVEMENTS?	VEGETATION REMOVAL?	REHABILITATION NEEDED	ESTIMATED COST	ENGINEERING & ADMINISTRATION	CONTINGENCIES	TOTAL COST FOR EACH POND	WORK PRIORITY	PRIORITY RANKING	TOTAL COST OF PROJECTS BY PRIORITY	YEARS TO COMPLETION WITH \$100,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$200,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$300,000 ANNUAL BUDGET <sup>1</sup>
32	Tirabassi		Wet		Yes	Yes	Repair orifice in outlet. Clear brush from outlet and pond perimeter. Repair erosion at west inlet structure.	\$5,000 \$5,000 \$5,000	\$1,800	\$2,520	\$19,320	Medium	2	\$179,032	4.5	2.2	1.5
42	Gangler	Yes	Wet		Yes	Yes	Clear debris and repair orifice in outlet structure; note if water level drops. Clear vegetation from structures and perimeter.	\$5,000 \$5,000	\$1,200	\$1,680	\$12,880	Medium	5				
38	Whitecaps A	Yes	Wet		Yes		Remove clog from outlet structure. Repair 18" and 30" inlet pipes.	\$5,000 \$2,000	\$840	\$1,176	\$9,016	Medium	8				
33	Anderson Park	Yes	Wet		Yes		Locate inlet/outlet structures and determine cause of pond overflow.	\$5,000	\$600	\$840	\$6,440	Medium	9				
27	89th/39th	Yes	Dry		Yes	Yes	Clean channels and structures and keep free of debris. Repair first orifice on outlet structure. Repair 18" inlet pipe.	\$2,000 \$5,000 \$2,000	\$1,080	\$1,512	\$11,592	Medium	10				
31	River Crossing	Yes	Dry		Yes	Yes	Clean channels and structures. Check structures for obstructions. Clear vegetation from spillway.	\$2,000 \$5,000 \$1,000	\$960	\$1,344	\$10,304	Medium	16				
39	Whitecaps B		Wet		Yes	Yes	Clear debris and repair outlet structure. Clear vegetation from structures, rip-rap, and perimeter.	\$5,000 \$5,000	\$1,200	\$1,680	\$12,880	Medium	17				
40	Whitecaps F		Wet	Yes	Yes		Dredge siltation basin to remove sediment. Repair inlet pipe.	\$10,000 \$2,000	\$1,440	\$2,016	\$15,456	Medium	18				
35	Nash Park	Yes	Wet	Monitor		Yes	Clear vegetation from inlet and outlet structures. Monitor sediment build-up in south end.	\$2,000 \$48,000	\$6,000	\$8,400	\$64,400	Medium	22				
44	Payne & Dolan Recycling		Wet	Monitor	Yes	Yes	Clean outlet structure. Remove silt fence from drainage swale. Clear cattails from pond and vegetation from rip-rap. Monitor need for dredging.	\$2,000 \$5,000 \$4,000	\$1,320	\$1,848	\$14,168	Medium	24				
23	Business Park B		Dry		Yes	Yes	Clear debris and vegetation from structures.	\$2,000	\$240	\$336	\$2,576	Medium	28				

NOTES:

1. Assumes 50% of budget to high-priority projects, 40% to medium-priority projects, and 10% to low-priority projects.

**2014 KENOSHA POND MAINTENANCE REQUIREMENTS  
CITY OWNED/MAINTAINED**

#	POND NAME	3 acres or more?	WET/ DRY	DREDGING?	INLET/OUTLET IMPROVEMENTS?	VEGETATION REMOVAL?	REHABILITATION NEEDED	ESTIMATED COST	ENGINEERING & ADMINISTRATION	CONTINGENCIES	TOTAL COST FOR EACH POND	WORK PRIORITY	PRIORITY RANKING	TOTAL COST OF PROJECTS BY PRIORITY	YEARS TO COMPLETION WITH \$100,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$200,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$300,000 ANNUAL BUDGET <sup>1</sup>
25	Petretti	Yes	Wet & Dry		Yes		Reattach 15" pipe. Clean sediment from concrete gutters.	\$1,000 \$2,000	\$360	\$504	\$3,864	Low	3	\$19,320	1.9	1.0	0.6
22	Business Park A	Yes	Dry			Yes	Clear debris from structures. Clear willow brush. Clean channel.	\$1,000 \$2,000 \$2,000	\$600	\$840	\$6,440	Low	5				
36	Hillside	Yes	Wet			Yes	Clear vegetation from outlet structure. Clean channels.	\$1,000 \$2,000	\$360	\$504	\$3,864	Low	8				
29	Whitecaps D		Dry		Yes		Clear debris from outlet structure.	\$1,000	\$120	\$168	\$1,288	Low	11				
30	Whitecaps C		Dry		Yes		Clear debris from outlet structure.	\$1,000	\$120	\$168	\$1,288	Low	12				
37	St. Peter's	Yes	Wet			Yes	Clear debris and vegetation from structures.	\$2,000	\$240	\$336	\$2,576	Low	14				

NOTES:

1. Assumes 50% of budget to high-priority projects, 40% to medium-priority projects, and 10% to low-priority projects.

**2014 KENOSHA POND MAINTENANCE REQUIREMENTS  
CITY OWNED/MAINTAINED**

#	POND NAME	3 acres or more?	WET/ DRY	DREDGING?	INLET/OUTLET IMPROVEMENTS?	VEGETATION REMOVAL?	REHABILITATION NEEDED	ESTIMATED COST	ENGINEERING & ADMINISTRATION	CONTINGENCIES	TOTAL COST FOR EACH POND	WORK PRIORITY	PRIORITY RANKING	TOTAL COST OF PROJECTS BY PRIORITY	YEARS TO COMPLETION WITH \$100,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$200,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$300,000 ANNUAL BUDGET <sup>1</sup>
41	Whitecaps G		Wet				None.				N/A						

NOTES:

1. Assumes 50% of budget to high-priority projects, 40% to medium-priority projects, and 10% to low-priority projects.

**2014 KENOSHA POND MAINTENANCE REQUIREMENTS  
PRIVATELY OWNED WITH MAINTENANCE AGREEMENT**

#	POND NAME	3 acres or more?	WET/ DRY	DREDGING?	INLET/OUTLET IMPROVEMENTS?	VEGETATION REMOVAL?	REHABILITATION NEEDED	ESTIMATED COST	ENGINEERING & ADMINISTRATION	CONTINGENCIES	TOTAL COST FOR EACH POND	WORK PRIORITY	PRIORITY RANKING	TOTAL COST OF PROJECTS BY PRIORITY	YEARS TO COMPLETION WITH \$100,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$200,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$300,000 ANNUAL BUDGET <sup>1</sup>
18	Peterson's Golden Meadow B2		Wet				None.				N/A						

NOTES:

1. Assumes 50% of budget to high-priority projects, 40% to medium-priority projects, and 10% to low-priority projects.

**2014 KENOSHA POND MAINTENANCE REQUIREMENTS  
PRIVATELY OWNED WITH MAINTENANCE AGREEMENT**

#	POND NAME	3 acres or more?	WET/ DRY	DREDGING?	INLET/OUTLET IMPROVEMENTS?	VEGETATION REMOVAL?	REHABILITATION NEEDED	ESTIMATED COST	ENGINEERING & ADMINISTRATION	CONTINGENCIES	TOTAL COST FOR EACH POND	WORK PRIORITY	PRIORITY RANKING	TOTAL COST OF PROJECTS BY PRIORITY	YEARS TO COMPLETION WITH \$100,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$200,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$300,000 ANNUAL BUDGET <sup>1</sup>
49	Gateway		Wet	Yes	Yes	Yes	Dredge to remove sediment and restore depth.	\$16,000	\$3,240	\$4,536	\$34,776	High	3	\$360,640	7.2	3.6	2.4
							Inspect functionality of inlet pipe and make necessary repairs.	\$5,000									
							Attach outlet pipe to structure.	\$1,000									
							Clear vegetation from structures and perimeter.	\$5,000									
56	Heritage Heights 2		Wet	Yes	Yes		Dredge to remove sediment and restore depth.	\$13,000	\$2,160	\$3,024	\$23,184	High	4	\$360,640	7.2	3.6	2.4
							Inspect inlet pipe and outlet structures and clear clogs.	\$5,000									
14	Menards	Yes	Wet	Yes	Yes	Yes	Remove vegetation around perimeter and structures.	\$2,000	\$19,920	\$27,888	\$213,808	High	7	\$360,640	7.2	3.6	2.4
							Clean all structures.	\$1,000									
							Install grates on 2 inlets.	\$1,000									
							Dredge pond to remove sediment.	\$162,000									
20	South Port Plaza Basin A	Yes	Wet	Yes			Dredge to remove sediment.	\$68,000	\$8,160	\$11,424	\$87,584	High	8				
10	LeMay Buick		Wet		Yes		Clean trash from structures.	\$1,000	\$120	\$168	\$1,288	High	9				

NOTES:

1. Assumes 50% of budget to high-priority projects, 40% to medium-priority projects, and 10% to low-priority projects.

**2014 KENOSHA POND MAINTENANCE REQUIREMENTS  
PRIVATELY OWNED WITH MAINTENANCE AGREEMENT**

#	POND NAME	3 acres or more?	WET/DRY	DREDGING?	INLET/OUTLET IMPROVEMENTS?	VEGETATION REMOVAL?	REHABILITATION NEEDED	ESTIMATED COST	ENGINEERING & ADMINISTRATION	CONTINGENCIES	TOTAL COST FOR EACH POND	WORK PRIORITY	PRIORITY RANKING	TOTAL COST OF PROJECTS BY PRIORITY	YEARS TO COMPLETION WITH \$100,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$200,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$300,000 ANNUAL BUDGET <sup>1</sup>
15	Midwest Transportation	Yes	Wet		Yes	Yes	Replace grate on outlet structure. Remove brush at north end and near 72" inlet.	\$1,000 \$2,000	\$360	\$504	\$3,864	Medium	1	\$926,072	23.2	11.6	7.7
47	Bradford Estates		Wet	Monitor	Yes		Bolt down loose grates on outlet structure. Clean grates on structures. Monitor need for dredging within next five years.	\$1,000 \$1,000 \$6,000	\$960	\$1,344	\$10,304	Medium	3				
1	Ansari (Barth Storage)		Wet		Yes	Yes	Replace bottom grate on outlet. Reattach end section on 60" inlet. Remove vegetation from rip-rap.	\$1,000 \$1,000 \$2,000	\$480	\$672	\$5,152	Medium	4				
6	Palmen Motors		Wet		Yes	Yes	Construct swale to nearby culvert to remedy drainage problem. Clear trees around outlet and spillway.	\$15,000 \$1,000	\$1,920	\$2,688	\$20,608	Medium	6				
5	Prairie Lake Estates (Heiberg)	Yes	Wet		Yes	Yes	Clean structures and remove vegetation from rip-rap. Inspect downstream channel for clogging.	\$2,000 \$1,000	\$360	\$504	\$3,864	Medium	7				
50	Hunters Ridge A		Wet		Yes	Yes	Clean pipe at southeast corner to remove clog. Clear vegetation from structures and pond perimeter.	\$2,000 \$5,000	\$840	\$1,176	\$9,016	Medium	11				
52	Hunters Ridge C		Wet		Yes	Yes	Reattach inlet pipe. Repair two eroded channels. Clear vegetation from structures and pond perimeter.	\$1,000 \$5,000 \$5,000	\$1,320	\$1,848	\$14,168	Medium	12				
51	Hunters Ridge B		Wet		Yes	Yes	Reattach end sections to inlet pipes. Clear vegetation from structures and pond perimeter. Inspect structures to determine cause of low water level.	\$2,000 \$5,000 \$5,000	\$1,440	\$2,016	\$15,456	Medium	13				
46	Woodman's Basin B		Wet		Yes	Yes	Clean vegetation from outlet structure and perimeter. Clean outlet to remove clog; note if water level drops. Clear pond area of debris.	\$5,000 \$5,000 \$1,000	\$1,320	\$1,848	\$14,168	Medium	14				
45	Woodman's Basin A		Wet	Yes		Yes	Dredge at south end and near outlet structure. Clear vegetation from structures and perimeter. Clear pond area of debris.	\$36,000 \$5,000 \$1,000	\$5,040	\$7,056	\$54,096	Medium	15				
43	Indian Trail Estates - YMCA	Yes	Wet		Yes	Yes	Clean vegetation from structures, rip-rap, and pond perimeter. Repair washed-out rip-rap.	\$5,000 \$2,000	\$840	\$1,176	\$9,016	Medium	19				
12	Leona's Rolling Meadows Subdivision C1		Wet	Yes		Yes	Dredge to remove sediment. Clear vegetation around pond.	\$23,000 \$2,000	\$3,000	\$4,200	\$32,200	Medium	20				
11	Leona's Rolling Meadows Subdivision C	Yes	Wet	Yes	Yes		Dredge to remove sediment. Clean outlet periodically.	\$133,000 \$1,000	\$16,080	\$22,512	\$172,592	Medium	21				
9	KM Property Owners South Port Plaza B		Wet	Monitor	Yes		Sediment is deep in some areas; monitor need for dredging over next five years. Clean outlet and check for blockage.	\$31,000 \$5,000	\$4,320	\$6,048	\$46,368	Medium	23				
53	Mahone	Yes	Wet	Monitor		Yes	Clear vegetation from structures, rip-rap, and north end of pond. Determine design depth of pond and whether dredging is necessary. Monitor need for dredging within next five years.	\$2,000 \$1,000 \$393,000	\$47,520	\$66,528	\$510,048	Medium	25				
2	Dairyland Greyhound Park (WEST)		Wet			Yes	Remove perimeter vegetation and locate structures.	\$2,000	\$240	\$336	\$2,576	Medium	26				
3	Dairyland Greyhound Park (NORTH)	Yes	Wet			Yes	Remove vegetation around perimeter and outlet structure.	\$2,000	\$240	\$336	\$2,576	Medium	27				

NOTES:

1. Assumes 50% of budget to high-priority projects, 40% to medium-priority projects, and 10% to low-priority projects.

**2014 KENOSHA POND MAINTENANCE REQUIREMENTS  
PRIVATELY OWNED WITH MAINTENANCE AGREEMENT**

#	POND NAME	3 acres or more?	WET/ DRY	DREDGING?	INLET/OUTLET IMPROVEMENTS?	VEGETATION REMOVAL?	REHABILITATION NEEDED	ESTIMATED COST	ENGINEERING & ADMINISTRATION	CONTINGENCIES	TOTAL COST FOR EACH POND	WORK PRIORITY	PRIORITY RANKING	TOTAL COST OF PROJECTS BY PRIORITY	YEARS TO COMPLETION WITH \$100,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$200,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$300,000 ANNUAL BUDGET <sup>1</sup>
16	Peterson's Golden Meadow A		Wet		Yes		Stabilize erosion near outlet structure and clean lower outlet.	\$5,000	\$600	\$840	\$6,440	Low	1	\$43,792	4.4	2.2	1.5
48	Regal Apartments		Wet		Yes	Yes	Repair end section on 18" pipe.	\$1,000	\$480	\$672	\$5,152	Low	2				
							Remove vegetation at structures and spillway.	\$2,000									
							Mow area around pond.	\$1,000									
7	Kenosha Trade Commerce		Wet		Yes		Reattach end section on 27" inlet.	\$1,000	\$120	\$168	\$1,288	Low	4				
54	Heritage Heights 1A		Wet			Yes	Clear vegetation from structures.	\$2,000	\$840	\$1,176	\$9,016	Low	6				
							Remove cattails from pond interior.	\$5,000									
55	Heritage Heights 1B		Wet			Yes	Clear vegetation from structures.	\$2,000	\$840	\$1,176	\$9,016	Low	7				
							Remove cattails from pond interior.	\$5,000									
19	North Point Subd. Prayer House of God		Wet			Yes	Remove vegetation from rip-rap and structures.	\$2,000	\$240	\$336	\$2,576	Low	9				
17	Peterson's Golden Meadow B1		Wet				Clear debris from grates.	\$1,000	\$120	\$168	\$1,288	Low	10				
28	Shagbark	Yes	Wet			Yes	Clear vegetation from inlet structure.	\$1,000	\$120	\$168	\$1,288	Low	13				
8	Kenosha Bible Church		Wet			Yes	Remove vegetation around perimeter and outlet structure.	\$2,000	\$240	\$336	\$2,576	Low	15				
13	Leona's Rolling Meadows Subdivision F		Wet			Yes	Remove vegetation from rip-rap.	\$2,000	\$240	\$336	\$2,576	Low	16				
4	Dairyland Greyhound Park (SOUTH)		Wet			Yes	Remove perimeter vegetation.	\$2,000	\$240	\$336	\$2,576	Low	17				

NOTES:


1. Assumes 50% of budget to high-priority projects, 40% to medium-priority projects, and 10% to low-priority projects.

**2014 KENOSHA POND MAINTENANCE REQUIREMENTS  
PRIVATELY OWNED WITH MAINTENANCE AGREEMENT**

#	POND NAME	3 acres or more?	WET/ DRY	DREDGING?	INLET/OUTLET IMPROVEMENTS?	VEGETATION REMOVAL?	REHABILITATION NEEDED	ESTIMATED COST	ENGINEERING & ADMINISTRATION	CONTINGENCIES	TOTAL COST FOR EACH POND	WORK PRIORITY	PRIORITY RANKING	TOTAL COST OF PROJECTS BY PRIORITY	YEARS TO COMPLETION WITH \$100,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$200,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$300,000 ANNUAL BUDGET <sup>1</sup>
18	Peterson's Golden Meadow B2		Wet				None.				N/A						

NOTES:

1. Assumes 50% of budget to high-priority projects, 40% to medium-priority projects, and 10% to low-priority projects.




- High Priority
- Medium Priority
- Low Priority
- No Maintenance Required
- City Limits

# Pond Maintenance Priorities

## City-Owned Ponds


City of Kenosha



Date Created: August 4, 2014

Path: R:\Kenosha\Projects\K0300080\_Kenosha-Pond Certs\City-Owned2.mxd





Hillside

Payne/Dolan Recycling

Nash Park

Kenosha Industrial Park

Gangler

Map Area


Note: Blue outline indicates area shown on this map

- High Priority
- Medium Priority
- Low Priority
- No Maintenance Required
- City Limits

# Pond Maintenance Priorities


## City-Owned Ponds

City of Kenosha



Date Created: August 4, 2014

Path: R:\Kenosha\Projects\K0300080\_Kenosha-Pond Certs\City-Owned4.mxd



Lincoln Park Lagoon

Anderson Park Pond

Tirabassi

89th St & 39th Ave


Map Area

Note: Blue outline indicates area shown on this map

- High Priority
- Medium Priority
- Low Priority
- No Maintenance Required
- City Limits


# Pond Maintenance Priorities City-Owned Ponds

City of Kenosha



Date Created: August 4, 2014

Path: R:\Kenosha\Projects\K0300080\_Kenosha-Pond Certs\City-Owned3.mxd



**Map Area**

Note: Blue outline indicates area shown on this map


- Low Priority
- No Maintenance Required
- Medium Priority
- High Priority
- City Limits

## Pond Maintenance Priorities Private-Owned Ponds

City of Kenosa

1 inch = 1,000 feet

Date Created: August 4, 2014  
Path: R:\Kenosa\Projects\K0300080\_Kenosa-Pond Certs\Private-Owned2.mxd



**Map Area**

Note: Blue outline indicates area shown on this map

- Low Priority
- No Maintenance Required
- Medium Priority
- High Priority
- City Limits

# Pond Maintenance Priorities Private-Owned Ponds

City of Kenosha



Date Created: August 4, 2014

Path: R:\Kenosha\Projects\K0300080\_Kenosha-Pond Certs\Private-Owned3.mxd

**Map Area**

Note: Blue outline indicates area shown on this map

Hunter's Ridge Subdivision - Pond A

Hunter's Ridge Subdivision - Pond B

Hunter's Ridge Subdivision - Pond C

North Pointe

Bradford Estates

Bradford - Shagbark

Regal

- Low Priority
- No Maintenance Required
- Medium Priority
- High Priority
- City Limits



## Pond Maintenance Priorities Private-Owned Ponds

City of Kenosha

1 inch = 1,000 feet

Date Created: August 4, 2014

Path: R:\Kenosha\Projects\K0300080\_Kenosha-Pond Certs\Private-Owned1.mxd



- Low Priority
- No Maintenance Required
- Medium Priority
- High Priority
- City Limits

## Pond Maintenance Priorities Private-Owned Ponds

City of Kenosha

Date Created: August 4, 2014

1 inch = 1,000 feet

Path: R:\Kenosha\Projects\K0300080\_Kenosha-Pond Certs\Private-Owned4.mxd

**PONDS OWNED AND MAINTAINED  
BY CITY OF KENOSHA**

**HIGH PRIORITY  
MAINTENANCE REQUIREMENTS**

**2014 KENOSHA POND MAINTENANCE REQUIREMENTS  
CITY OWNED/MAINTAINED**

#	POND NAME	3 acres or more?	WET/ DRY	DREDGING?	INLET/OUTLET IMPROVEMENTS?	VEGETATION REMOVAL?	REHABILITATION NEEDED	ESTIMATED COST	ENGINEERING & ADMINISTRATION	CONTINGENCIES	TOTAL COST FOR EACH POND	WORK PRIORITY	PRIORITY RANKING	TOTAL COST OF PROJECTS BY PRIORITY	YEARS TO COMPLETION WITH \$100,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$200,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$300,000 ANNUAL BUDGET <sup>1</sup>
34	Lincoln Park	Yes	Wet	Yes	Yes	Yes	Dredge to remove sediment.	\$247,000	\$31,440	\$44,016	\$337,456	High	1	\$516,488	10.3	5.2	3.4
							Clear vegetation from north end and inlet.	\$5,000									
							Replace outlet structure.	\$10,000									
24	Kenosha Industrial Park	Yes	Dry	Yes		Yes	Dredge to original design elevations to restore function.	\$103,000	\$12,960	\$18,144	\$139,104	High	2				
							Clear vegetation within and surrounding pond.	\$5,000									
21	Bullen	Yes	Dry		Yes		Remove clog from outlet.	\$2,000	\$720	\$1,008	\$7,728	High	5				
							Clean flow channel.	\$2,000									
							Clean sediment from outlet structure.	\$2,000									
26	Whitecaps E	Yes	Dry	Yes	Yes	Yes	Dredge siltation basin.	\$17,000	\$3,000	\$4,200	\$32,200	High	6				
							Clean 8" pipe and concrete gutters.	\$5,000									
							Remove vegetation from structures.	\$2,000									
							Install grate on upper outlet.	\$1,000									

NOTES:

1. Assumes 50% of budget to high-priority projects, 40% to medium-priority projects, and 10% to low-priority projects.

Ponds Owned and Maintained  
by City of Kenosha  
Lincoln Park



January 15, 2014

### Measurement Results for Lincoln Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
N/A	N/A	2.6 – 5.6	2018

### Notes

1. The measured water depth in July of 2013 varied between 2.6 feet and 5.6 feet. The original design plans were not available.
2. The inlets and outlets were inspected and were in good condition.
3. Sediment build-up varied between 0.6 and 2.5 feet, with the thicker silt at the north end of the pond.
4. There is thick cattail growth at the north end of the pond and also in the inlet channel at the south end of the pond. Algae covered most of the pond.
5. The function of the outlet structure is unclear.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the post-dredging measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for the next sediment removal.
2. The outlet structure requires further investigation. Replacement may be necessary if the structure is not functional.
3. The cattails and willows should be cleared from both the north end and the inlet channel.
4. Dredge to remove sediment.




7-3-3 A, 46 CUTO

N↑

**LINDEN PARK**


- DEPTHS

PK	DEPTH	DESCRIPTION	PK	DEPTH	DESCRIPTION
30,069	5.17.0	10.5 ABOVE CURB (OFFLOW)	30,274	1.0	- R.C.P. (E.F. 30.069)
	5.6.8.1		30,280	5.0	STEEL W/ R.C.P.
	5.0/5.16		30,282	PK 30,069	
	4.0/5.14		216,555-873	552618.612	19.064
	4.274.6		30,284	PK 30,069	
	2.6	- 2x2 20"	216,622-373	2552656.000	6.5'3
			30,285	PK 30,069	
			215,562-236	2552404.112	19.748
			30,289	PK 30,069	
			215,544	PK 30,069	



LINCOLN PARK LAGOON

EAST SIDE INTAKE - SEE NO. (N) OF BRIDGE  
ON -- OF POND.



# LINCOLN PARK


WATER ELEV.= 607.4

DEPTHS BELOW WATER

4.1 (TOP SEDIMENT)

4.5 (BOTTOM)

WATER SURFACE AREA = 182,450 SF



NOV./2013

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

**Clark Dietz**  
ENGINEERS

K0300080

**Ponds Owned and Maintained  
by City of Kenosha  
Kenosha Industrial Park**



July 10, 2013

### Measurement Results for Kenosha Industrial Park Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1980	4	1 – 1.5	2018

### Notes

1. The designed water depth of the pond is approximately 4 feet; the design plans are not clear. The measured water depth in February of 2013 varied between 1 and 1.5 feet. We conclude that the pond is filling with sediment.
2. The pond does not seem to be functioning correctly. The area around the outlet pipe was dry while there was stagnant water in the ends of the pond.
3. The inlet and outlet structures were inspected and were found to be in good structural condition.
4. Sediment build-up varies between 1 and 1.5 feet.
5. The pond is completely full of cattails and there is extensive brush growth on the edges. Vegetation has also grown up around the inlets and outlets.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements.
2. Since the pond is no longer functioning, it should be recut to its original design elevations. Further investigation into the original design of the pond is needed.
3. The cattails and brush within and surrounding the pond should be removed.











2-6-13

GENERAL INDUSTRIAL PARK

RENUMBER SHEDS IN THE YARD  
TO 2000+

2/14/13 360 AT RB

2250-2364

FEND # 2364

\* RESTRICTOR ?


\* HOW IS POND SUPPOSED TO WORK?  
(DOX LEAKS NEAR CURB, SWAMPY WATER  
E FENDS)

- LOT OF MAINTENANCE REQ'D

- TREES I BEWISH

- RE-CUT POND

(9)



SHUTE - 11W = 25  
T.O.P. - 11W = 3.8



T.O.P. - 6.3

# KENOSHA INDUSTRIAL PARK

WATER ELEV. -- VARIES  
(DRY BOTTOM DESIGN)

DEPTHS BELOW WATER

0.0 (TOP SEDIMENT)  
◆  
0.0 (BOTTOM)





**Clark Dietz**  
ENGINEERS

FEB./2013

K0300080

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

Ponds Owned and Maintained  
by City of Kenosha  
Bullen



January 14, 2014

### Measurement Results for Bullen Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Inspection
N/A	N/A	N/A	2018

### Notes

1. The dry bottom pond was inspected in June and August of 2013. The original design plans were not available.
2. The channel and structures were flooded during both the June and August inspections. The outlet structure seemed clogged at the orifice.
3. There was heavy silt in the flow channel.
4. The rip-rap area near the flared end section is heavily eroded and silted. Sediment is heavy at the outlet structure.

### RECOMMENDATIONS

1. The pond should be inspected again in 2018.
2. The outlet structure should be inspected to determine if there is a clog at the orifice and if additional actions are needed.
3. The flow channel should be cleaned.
4. Cleaning and maintenance is required at the outlet structure to remove the built-up sediment and silt.








1 Bulletin


6-26-13  
18100 - 13400 - 18540  
6-26-13 close

8/22 Channel & Structures still flooded  
overflow structure seems clogged at orifice




\* FLOW CHANNEL: NEEDS  
CLEANING.  
\* RO-RIP AREA AROUND BRIDGE RES. NEEDS  
PROPOSED S. NEEDS MAINTENANCE.


EAST STRUCTURE




WEST STRUCTURE



**BULLEN  
DRY POND**



**WEST STRUCTURE**



**EAST STRUCTURE**


WEST STRUCTURE  
INV 644.6  
V-SHAPED STRUCTURE  
60" RCP @ 647.1

EAST STRUCTURE  
INV 648.2  
V-SHAPED STRUCTURE WITH  
SWINGING GATE FOR 12" RCP  
4.5'x5' GRATES (X3)  
24" RCP OUTLET @ 645.3

48" W X 30" H RCP

RIP RAP

CONCRETE CHANNEL



**Clark Dietz**  
ENGINEERS

JUNE/2013

K0300080

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

Ponds Owned and Maintained  
by City of Kenosha  
Whitecaps E



October 31, 2013

### Measurement Results for WhiteCaps E Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1990	6.4	1.5	2018

### Notes

1. The designed water depth of the small siltation basin at this dry pond is 6.4 feet. The measured water depth in February of 2013 was 1.5 feet. The basin is full of sediment.
2. The inlet and outlet pipes were inspected. There was debris on the outlet structure. The size of the outlet orifice could not be determined.
3. Sediment build-up in the siltation basin measured 1.5 feet.
4. The 8-inch pipe between the west structure and the siltation basin is dirty and clogged.
5. There is muck in the concrete gutters.
6. Willows are growing near the siltation basin.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. If the siltation basin is necessary or desired, dredging is recommended.
3. Clean the 8-inch pipe and clear all structures of vegetation.
4. Scrape the muck from the concrete gutters.
5. Further investigation of the outlet structure is necessary to determine elevations.
6. Install a fence or grate on the upper outlet structure.









2/26/13 AT, BB Cloudy 31°  
windy

WHITECAPS BASIN E


# 5500

MAINT. NEEDS

- hump windows
- CHECK OUT 8" FROM W. BASIN TO "POND"
- SCRAP MUD FROM LUTITE
- 15" POND HREED or DESIGNED?  
(FILL IN & KEEP OPEN)  
OR DEBRIS FROM
- DEBRIS ON OUTLET

• NEED - COLL. GUTTERS ✓

- LOWER OUTLET STR. ✓
- "WEST POND" ✓ N/A D=1.5 (max 1.5)
- LOWER O.FLOW CANAL ✓
- FENCE ON UPPER AVENUE ✓



(19)

HEAD  
BOTTOM



# WHITECAPS - BASIN E

WATER ELEV.  
702.7

## DEPTHS BELOW WATER

1.5 (TOP SEDIMENT)  
3.0 (BOTTOM)

WATER SURFACE AREA = 5,151 SF





**Clark Dietz**  
ENGINEERS

FEB./2013

K0300080

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

**MEDIUM PRIORITY  
MAINTENANCE REQUIREMENTS**

**2014 KENOSHA POND MAINTENANCE REQUIREMENTS  
CITY OWNED/MAINTAINED**

#	POND NAME	3 acres or more?	WET/DRY	DREDGING?	INLET/OUTLET IMPROVEMENTS?	VEGETATION REMOVAL?	REHABILITATION NEEDED	ESTIMATED COST	ENGINEERING & ADMINISTRATION	CONTINGENCIES	TOTAL COST FOR EACH POND	WORK PRIORITY	PRIORITY RANKING	TOTAL COST OF PROJECTS BY PRIORITY	YEARS TO COMPLETION WITH \$100,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$200,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$300,000 ANNUAL BUDGET <sup>1</sup>
32	Tirabassi		Wet		Yes	Yes	Repair orifice in outlet. Clear brush from outlet and pond perimeter. Repair erosion at west inlet structure.	\$5,000 \$5,000 \$5,000	\$1,800	\$2,520	\$19,320	Medium	2	\$179,032	4.5	2.2	1.5
42	Gangler	Yes	Wet		Yes	Yes	Clear debris and repair orifice in outlet structure; note if water level drops. Clear vegetation from structures and perimeter.	\$5,000 \$5,000	\$1,200	\$1,680	\$12,880	Medium	5				
38	Whitecaps A	Yes	Wet		Yes		Remove clog from outlet structure. Repair 18" and 30" inlet pipes.	\$5,000 \$2,000	\$840	\$1,176	\$9,016	Medium	8				
33	Anderson Park	Yes	Wet		Yes		Locate inlet/outlet structures and determine cause of pond overflow.	\$5,000	\$600	\$840	\$6,440	Medium	9				
27	89th/39th	Yes	Dry		Yes	Yes	Clean channels and structures and keep free of debris. Repair first orifice on outlet structure. Repair 18" inlet pipe.	\$2,000 \$5,000 \$2,000	\$1,080	\$1,512	\$11,592	Medium	10				
31	River Crossing	Yes	Dry		Yes	Yes	Clean channels and structures. Check structures for obstructions. Clear vegetation from spillway.	\$2,000 \$5,000 \$1,000	\$960	\$1,344	\$10,304	Medium	16				
39	Whitecaps B		Wet		Yes	Yes	Clear debris and repair outlet structure. Clear vegetation from structures, rip-rap, and perimeter.	\$5,000 \$5,000	\$1,200	\$1,680	\$12,880	Medium	17				
40	Whitecaps F		Wet	Yes	Yes		Dredge siltation basin to remove sediment. Repair inlet pipe.	\$10,000 \$2,000	\$1,440	\$2,016	\$15,456	Medium	18				
35	Nash Park	Yes	Wet	Monitor		Yes	Clear vegetation from inlet and outlet structures. Monitor sediment build-up in south end & need for dredging in next 5 years.	\$2,000 \$48,000	\$6,000	\$8,400	\$64,400	Medium	22				
44	Payne & Dolan Recycling		Wet	Monitor	Yes	Yes	Clean outlet structure. Remove silt fence from drainage swale. Clear cattails from pond and vegetation from rip-rap. Monitor need for dredging in next five years.	\$2,000 \$5,000 \$4,000	\$1,320	\$1,848	\$14,168	Medium	24				
23	Business Park B		Dry		Yes	Yes	Clear debris and vegetation from structures.	\$2,000	\$240	\$336	\$2,576	Medium	28				

NOTES:

1. Assumes 50% of budget to high-priority projects, 40% to medium-priority projects, and 10% to low-priority projects.

Ponds Owned and Maintained  
by City of Kenosha  
Tirabassi



September 3, 2013

### Measurement Results for Tirabassi Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1998	5 & 13	5.4 – 15.8	2018


### Notes

1. The designed water depth of most of the pond is 5 feet, with a section designed for a normal depth of 13 feet. The measured water depth in June of 2013 varied between 5.4 and 15.8 feet. We conclude that the pond was over-excavated at the time of construction.
2. One orifice opening in the outlet structure is broken. There is also heavy brush and plant growth around the outlet structure.
3. The west inlet structure is full of clay silt. This indicates an erosion issue.
4. Sediment build-up varied between 0.3 and 1.4 feet.
5. The pond perimeter area is occasionally mowed. Brush has grown up around most of the pond.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. Repair the orifice opening in the outlet structure.
3. Clear the brush from the outlet structure and remove other growth around the pond as necessary.
4. Investigate and repair the cause of the siltation problem at the west inlet structure.







6/3/13 AT 44 Sunny 70°

TIRABASSI


#14400 - 14638

MAINTENANCE

- BRUSH SCUB & DREDGE/CLEAN AROUND OUTLET
- IN INLET PIPE MUST HAVE BAD FRACTION ISSUES/SILTED IN W/CLAY SILT

6/20/13 WTR RUN = 611,40

4140	61,6.5	14651	5.4, -
	13,13.0	12.0	12.9, 13.7
	9.4, 10.8		15.8, 16.2
	10.0, -		14.1, 14.9
	13.9, 14.5	14655	9.3, 9.7
	6.1, 6.4		
	11.1, 11.7		
	5.6, 6.1		
4690	14.3, 14.7		
	6.8, -		
	14.8, 15.3		



**TIRABASSI**




WATER ELEV.= 611.4

DEPTHS BELOW WATER

10.7 (TOP SEDIMENT)

12.1 (BOTTOM)

WATER SURFACE AREA = 287,868 SF



**Clark Dietz** ENGINEERS  
K0300080

JUNE/2013

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

Ponds Owned and Maintained  
by City of Kenosha  
Gangler



September 3, 2013

### Measurement Results for Gangler Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2001	4.4	5.6 – 6.6	2018

### Notes

1. The designed water depth of the pond is 4.4 feet. The measured water depth in May of 2013 varied between 5.6 and 6.6 feet.
2. There is a broken orifice opening in the lower outlet structure. There was also some brush and debris buildup at the outlet structure.
3. Sediment build-up varied between 0 and 0.8 feet.
4. The pond perimeter has been mowed occasionally.
5. Soft ground was found on the west side of the pond, indicating groundwater seepage.
6. The water level is higher than the knee wall of the inlet structure.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. Brush should be removed near the outlet structure and the orifice opening should be repaired. The outlet should be kept clean.
3. Remove brush as necessary around the perimeter of the pond.
4. The high water level indicates that the pond may not be draining properly. Record whether repairs to the outlet structure decrease the water level.

















**GANGLER**



WATER ELEV. = 668.9

DEPTHS BELOW WATER

6.0 (TOP SEDIMENT)

6.2 (BOTTOM)


WATER SURFACE AREA = 201,900 SF



**OUTLET STRUCTURE**

BUSTED OPENING  
ORIFICE ±16"  
● 667.7

(4) 1'X5.5'  
GRADED OPENINGS



**SECTION A-A**


LOWER OUTLET STRUCTURE  
INV ● 668.3  
BUSTED OPENING ORIFICE  
±16" ● 667.7  
GRADED OPENINGS 1'X5.5' ● 671.5  
BOLTED RIM ● 675.2

INTERMEDIATE STRUCTURE  
4'X5' GRADED OPENING  
IN-SPILL 678.9  
42" OUTLET ● 668.3

UPPER STRUCTURE  
(3) 3.5'X5' GRADED BAYS  
OUTER BAYS CONNECTED TO  
INNER W/30" RCP ● 679.1  
INNER BAY DROPS W/4"  
STRUCTURE INTO 42" RCP  
OUTLET ● 667.4

55TH AVE

80TH ST



MAY/2013

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

**Clark Dietz**  
ENGINEERS

K0300080

Ponds Owned and Maintained  
by City of Kenosha  
Whitecaps A



July 10, 2013

### Measurement Results for WhiteCaps A Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1996	6	5.6 – 7.8	2018

### Notes

1. The designed water depth of the pond is 6 feet. The measured water depth in March of 2013 varied between 5.6 and 7.8 feet. We conclude that the pond was over-excavated at the time of construction.
2. The final section on the 18" pipe is completely separated. The final section on the 30" pipe is beginning to separate.
3. The lower orifice on the outlet is plugged.
4. Sediment build-up varies between 0.5 and 1.1 feet.
5. The whole pond perimeter is mowed.
6. The pond is functioning at the second overflow level.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. Perform dredging at the outlet to remove clogging materials.
3. Make repairs to the end sections on the 18" and 30" pipes.
4. When mowing, leave a grass strip around the pond to improve safety and deter geese.





3-29-13 sunny 40°



AT, BS

WHITECAPS BASIN A

Street # 7800, 7930 → 7975

- \* DRAINAGE & OUTLET (GREASE & SLUDGE)
- \* OUTLET LOWER ORIFACE PLUGGED, D.I REDUCER SIZE 3" x 5" φ
- \* 30" x 18" F.E.S. SEPARATED 18" IS COMPLETELY "
- \* POND IS FUNCTIONING & 2<sup>ND</sup> MAX. O/FLOW LEVEL
- OTHERWISE POND IN GOOD SHAPE

U-27-13	7930	7948	6.4, 7.5
	7969	7972	7.6, 8.1
	7970	7975	7.7, 8.8
	7971		7.8, 8.9
	(-7973)		7.6, 8.3



# WHITECAPS - BASIN A


WATER ELEV. = 704.7

DEPTHS BELOW WATER

0.0 (TOP SEDIMENT)

0.0 (BOTTOM)

WATER SURFACE AREA ± 55,390 SF



**OUTLET STRUCTURE**



OUTLET STRUCTURE  
4'x3' OPEN TOP  
BAY WALL (TOP=707.6)  
1'H X 2.5'W OPENING @ 704.5  
HAS 2"X3" D.I. REDUCER @ 703.8  
OUTLET 18" ORIFICE @ 703.7

CONCRETE SPILLWAY  
CREST=707.9

104TH AVE

ENTRANCE

OVERFLOW




**Clark Dietz**  
ENGINEERS

FEB./2013

K0300080

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

Ponds Owned and Maintained  
by City of Kenosha  
Anderson Park



October 31, 2013

### Measurement Results for Anderson Park Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
N/A	N/A	4.9 – 8.0	2018

### Notes

1. The measured water depth in May of 2013 varied between 4.9 to 8.0 feet. The original design plans were not available.
2. The structures were inspected. One submerged inlet pipe was found. No outlet structure was visible. There is also no spillway.
3. Sediment build-up varied between 0.3 and 2.3 feet.
4. The whole pond perimeter is mowed. There are some pockets of willow scrub.
5. The water level appeared high. Water had overflowed the pond in one area.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. Further investigation is necessary to locate the outlet structure and determine why it is not functioning properly.
3. Leave a one-foot wide strip around the pond when mowing to deter geese.





877-347-7750

S-24-13 AS, H1A SWAN 450



ANDERSON PACIFIC

# 13800

- \* ONLY 1 SUBMERGED PIPE
- \* NO OUTLET VISIBL
- NO SPILLWAYS

\* SWAN POISSON OF WILLOW SCRUB

# 14031 4.0, 6.9  
 4.5, 6.8  
 6.3, 6.6  
 7.5, 6.2  
 4.9, 5.5  
 6.7, 8.2  
 7.4, 7.9  
 8.0, 10.3  
 7.3, 8.3  
 7.7, 8.4  
 7.8, 8.2  
 14041 14061  
 8.0 14052



(75)

ANDERSON PARK


WATER ELEV.= 622.1

DEPTHS BELOW WATER


6.7 (TOP SEDIMENT)

7.6 (BOTTOM)

WATER SURFACE AREA = 291,228 SF



OUTLET STRUCTURE



**Clark Dietz**  
ENGINEERS

MAY/2013

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

K0300080

Ponds Owned and Maintained  
by City of Kenosha  
89<sup>th</sup>/39<sup>th</sup>



June 20, 2013

### Measurement Results for 89<sup>th</sup> and 39<sup>th</sup> Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Inspection
1983	N/A	N/A	2018

### Notes


1. This dry-bottom pond was inspected in May of 2013.
2. The first orifice opening on the outlet structure is broken.
3. The inlet and outlet structures were clogged with grass clippings and debris.
4. The pond area had been mowed earlier in the spring.
5. The concrete channels were coated with mud.
6. The frame on the 18" inlet pipe was offset, creating a dangerous condition.

### RECOMMENDATIONS


1. The pond should be inspected in 2018 to compare to the 2013 findings.
2. The concrete channels should be scraped clean.
3. The inlet and outlet structures should be cleaned and maintained regularly.
4. The first orifice in the outlet should be repaired.
5. Repair the 18" inlet pipe.
6. Remove grass clippings from the structures after mowing.













5-23-13 AT, 46' away 50'

89th ST & 39th AVE

# 13500 → 13730

- \* PRIMARY WURT BUSTED TO 7/18" φ
- \* SURFACE OUT BUTTERS
- \* WERE OUTLET LEAVE FREE OF DEBRIS
- \* MOVED LEASS CLIPPING CUB. STRUCTURES


HW LOW 89 ST



73

# 89TH/39TH

DRY BOTTOM





UPPER STRUCTURE  
 (3) 3.5'x5' GRATED BAYS  
 OUTER BAYS CONNECTED TO  
 INNER W/ 30" RCP @ 639.6  
 INNER BAY DROPS W/4"φ  
 STRUCTURE INTO 36" RCP  
 OUTLET @ 635.8

INTERMEDIATE STRUCTURE  
 4'x5' GRATED OPENING  
 IN-SPILL 642.7  
 36"φ OUTLET @ 635.9

LOWER OUTLET STRUCTURE  
 INV @ GUTTER = 635.9  
 BUSTED OPENING ORIFICE  
 ±18" @ 635.7  
 GRATED OPENINGS  
 1'x5.5' @ 638.9  
 BOLTEO RIM @ 642.6

OUTLET STRUCTURE

89TH ST.



RIM=655.9  
 IE=652.2 NW  
 IE=642.1 SE

18"φ RCP  
 PLATED  
 IE=641.1



MAY/2013

5017 GREEN BAY ROAD  
 SUITE 126  
 KENOSHA, WI 53144  
 PHONE : 262.657.1550  
 FAX : 262.657.1594

K0300080

Ponds Owned and Maintained  
by City of Kenosha  
River Crossing



July 16, 2013

### Measurement Results for River Crossing Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Inspection
N/A	N/A	1.5	2018

### Notes

1. There was approximately 1.5 feet of standing water in this dry-bottom pond when it was inspected in May of 2013. The original design plans were not available.
2. The inlets and outlets were inspected and were found to be in good structural condition. There is standing water over the beehive structure, however, indicating it is not functioning. The outlet structure is operating, at the level of the second orifice.
3. There was approximately 1.5 feet of sediment build-up underneath the standing water.
4. The pond had not been mowed due to the wet conditions. Trees and brush are growing adjacent to the concrete spillway.

### RECOMMENDATIONS

1. The pond should be inspected in 2018 to compare to the 2013 measurements.
2. All outlet structures should be cleaned and checked for possible obstructions.
3. The concrete channel should be cleaned.
4. The trees and brush near the spillway should be cleared.







# TO START  
12,500



5-14-13 AT (SUNNY 65°)

RIVER CROSSING


- + OPERATING & 2ND RAMP OVERFLOW
- \* TREES & BRUSH & SPILLWAY
- + LIGHT MAINT (SCRAPE COUL CHANNEL CLEAN OUT FWD SECTIONS)

PILOT SHOTS (EOL MEAD. CEDS) #12900 → 12850

→ TOWER = TREE 2



**RIVER CROSSING**  
**DRY BOTTOM**




**Clark Dietz**  
 ENGINEERS

MAY./2013  
 5017 GREEN BAY ROAD  
 SUITE 126  
 KENOSHA, WI 53144  
 PHONE : 262.657.1550  
 FAX : 262.657.1594

**K0300080**

Ponds Owned and Maintained  
by City of Kenosha  
Whitecaps B



July 10, 2013

### Measurement Results for WhiteCaps B Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1992	6	5.3 – 7.5	2018

### Notes

1. The designed water depth of the pond is 6 feet. The measured water depth in March of 2013 varied between 5.3 and 7.5 feet. We conclude that the pond was over-excavated at the time of construction.
2. The outlet structure is not functioning correctly. It is operating at the secondary overflow level since the lower restrictor orifice is clogged. There is also rip-rap inside the structure.
3. Sediment build-up averages 1.0 feet, with a minimum measurement of 5" and a maximum of 2.3'.
4. Cattails and willow are growing around most of the pond perimeter.
5. The rip-rap areas are silted and overgrown.
6. The inlet and outlet structures are overgrown with vegetation.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. Vegetation around the inlet and outlet structures and within rip-rap should be cleared, along with thick growth in other areas.
3. The outlet structure should be cleared of debris and repaired as necessary.









3-29-13 SU 40

AT, B.B


WHITE CAPS BASIN B

START # 8000-

- \* WILSON BASIN / CONTAINS
- \* RIP RAP SLOTTED & OVERFLOW
- \* OUTLET STRUCTURE NOT FUNCTIONING PROPERLY
- OPERATING @ 2" KEY OVERFLOW LEVEL
- RIP RAP LAYS OVER
- LANE RESTRICTION COLLIDED

6-27-13

# 8160	5.3, 6.2
61	7.0, 8.0
62	7.0, 8.3
63	6.5, 7.4
8164	7.5, 9



64TH ST.

### WHITECAPS - BASIN B

WATER ELEV. = 704.4

#### DEPTHS BELOW WATER

0.0 (TOP SEDIMENT)

◆ 0.0 (BOTTOM)

WATER SURFACE AREA = 32,090 SF

104TH AVE

IE=702.3  
24" RCP  
END SECTION

5.3  
◆ 6.2

7.4  
◆ 4.8

IE=713.8  
18" RCP  
END SECTION

7.5  
◆ 8.7

7.0  
◆ 8.3

6.5  
◆ 7.4

CONCRETE SPILLWAY  
CREST=709.8

OVERFLOW

1.8'H X 2.0'W  
OPENING @ 704.5


OUTLET STRUCTURE  
4'x3' OPEN TOP  
BAY WALL (TOP=707.5)  
1.8'H X 2.0'W OPENING @ 704.5  
HAS ?"X?" D.I. REDUCER @ 701.7  
OUTLET 12" ORIFICE @ 702.2

12" OUTLET ORIFICE  
IE=702.2

RESTRICTOR ORIFICE  
IE=701.7

#### OUTLET STRUCTURE

IE=706.8  
18" RCP  
END SECTION



FEB./2013

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

**Clark Dietz**  
ENGINEERS

K0300080

Ponds Owned and Maintained  
by City of Kenosha  
Whitecaps F



July 10, 2013

### Measurement Results for WhiteCaps F Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1992	4	2.5 – 3.1	2018

### Notes

1. The designed water depth of the pond is 4 feet. The pond consists of a wet area at the east end and a dry detention area. The measured water depth in March of 2013 varied between 2.5 and 3.1 feet. The dry area had a few scattered puddles. We conclude that the pond is starting to fill up with sediment.
2. The outlet structure is in good condition but the final section of the inlet is separated from the pipe.
3. Sediment build-up in the pond averages 1.0 feet.
4. The dry detention area and the pond perimeter are mowed.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. When mowing, leave a grass strip around the perimeter of the pond to improve safety and deter geese.
3. Dredging of the pond should be considered.







3-29-2013

Sunny, 40°

AT, BB

WHITE CAPS BASIN F'

START # 8300

\* F.E.S. SEPARATED @ CONNECTION JOINT

4-27-13

# 8482 EWATC → 8496

8497-2.7, 3.0


3.0, 4.1

- 2.5, 3.0

8683 3.1, 4.0

4" x 36"

GRATE



2" RCP  
-4.6

(37)


MH IN  
SIDEWALK

SEPARATED  
& FES  
CONNECTION

WATER  
(POND)



2" RCP  
- CATCH  
BASIN



N

# WHITECAPS - BASIN F



WATER ELEV.= 722.3

## DEPTHS BELOW WATER


0.0 (TOP SEDIMENT)

0.0 (BOTTOM)

WATER SURFACE AREA = 9,213 SF



OUTLET STRUCTURE





**Clark Dietz**  
ENGINEERS

FEB./2013

K0300080

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

Ponds Owned and Maintained  
by City of Kenosha  
Nash Park



September 5, 2013

### Measurement Results for Nash Park Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2001	12	9 – 12.2	2018


### Notes

1. The designed water depth of the pond is 12 feet. The measured water depth in June of 2013 ranged between 9.0 and 12.2 feet. The south end of the pond is shallower than the rest.
2. The inlet and outlet structures were inspected and were found to be in good condition.
3. Sediment build-up of 0.4 feet was found in one location.
4. The whole pond perimeter is mowed. Vegetation has grown up in certain areas around the pond, including near the outlet and inlets.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. Spotty brush removal is necessary, especially around the inlet and outlet structures.
3. The south area of the pond may be filling with sediment, creating the shallower depth. Future dredging of this area may be necessary.






6/13/13 - sunny 75° AT

ALASH PARK

street # 14800 → 14910 / S300 →  
MAINTENANCE

SPOTTY SAPPHIRE CAMERA

7-2-13	7:20
309089	9.07 9.14
	9.17 -
	12.00 -
	11.00 -
	12.11 -
	12.21 -



NASH PARK


WATER ELEV.=704.3

DEPTHS BELOW WATER


11.1 (TOP SEDIMENT)

- (BOTTOM)

WATER SURFACE AREA = 1,430,908 SF




OUTLET STRUCTURE



OUTLET STRUCTURE  
 2'X10.5' INV. @ 703.8  
 IN-SPILL WALL (TOP=704.5)  
 10"Ø ORIFICE @ 703.8  
 TOP WALL @ 707  
 OUTLET PIPE = 18" RCP

60TH ST



 <p><b>Clark Dietz</b> ENGINEERS</p>	JUNE/2013		
		K0300080	
			5017 GREEN BAY ROAD SUITE 126 KENOSHA, WI 53144 PHONE : 262.657.1550 FAX : 262.657.1594

Ponds Owned and Maintained  
by City of Kenosha  
Payne & Dolan Recycling



July 22, 2013

### Measurement Results for Payne & Dolan Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1996	5	4.5	2018

### Notes

1. The designed water depth of the pond is 5 feet. The measured water depth in May of 2013 was 4.5 feet. The pond may be starting to fill with sediment.
2. The outlet pipe was inspected and was found to be in good structural condition. The structure interior was dirty.
3. An old piece of silt fence is crossing one of the drainage swales into the pond.
4. Sediment depth varied from 0.2 to 0.4 feet.
5. The pond perimeter had not been mowed. Rip-rap areas have vegetation growing in them.
6. Cattail growth is overtaking the pond.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. Cattails should be removed from the pond and vegetation should be removed from the rip-rap.
3. The outlet structure should be cleaned.
4. Remove the silt fence from the drainage swale.
5. Dredging of this small pond may be necessary within the next five years.







PAYNE & DOLAN

WATER ELEV.= 708.1

DEPTHS BELOW WATER


0.0 (TOP SEDIMENT)



0.0 (BOTTOM)


WATER SURFACE AREA = 4,587 SF

46TH ST.




OUTLET STRUCTURE  
5'ø W/GRATED TOP @ 712.2  
3'x2' PRIMARY INLET GRATE  
ORIFICE=2"ø @ 707.8  
24" OUTLET @ 705.0

56TH AVE.



OUTLET STRUCTURE



MAY./2013  
**Clark Dietz**  
ENGINEERS  
K0300080

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

Ponds Owned and Maintained  
by City of Kenosha  
Business Park B



July 11, 2013

**Measurement Results for Business Park Basin B Pond**

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2003	NA	NA	NA

**Notes**

1. This dry bottom pond was inspected in February of 2013.
2. The inlet and outlet structures were inspected and were in good condition.
3. Some muck has built up around the structures and plugged the holes on the sides.
4. The pond area is mowed.

**RECOMMENDATIONS**

1. The pond should be inspected again in 2018.
2. Long grass, vegetation, and muck should be cleared away from the structures as necessary.



2-20-2013 - THURSDAY  
 BUSINESS Park KENOSHA - BASIN B  
 BB, TEMP: 25° F, CLOUDY  
 START: 10:15 EMPD

START POINT #4000 → 4294

#4001

#4181 - 18" RCP F.E.S.

#4192 - (38" x 24") EMPTICAL RCP F.E.S.

#4027 - 28" x 15" RCP F.E.S. (EMPTICAL)

#4087 - 36" x 21" RCP F.E.S. (ARCH TYPE)

#4122 - 51.4' x 5.4' GATE, 24" RCP (SE)

END 4262 → 4274

NEED - CB (OUTLET) ✓

F CHANNEL (S.E. CORNER)




- NEW PIPE SIZE 5V

MAINT ISSUES: MUCK GROUND UP c 2" HOLES

14" RCP -3.1

PROFILE

DOME STYLE OPEN LID




# KENOSHA BUSINESS PARK – BASIN B

DRY BOTTOM

58TH PLACE

88TH AVE

60TH STREET



**Clark Dietz**  
ENGINEERS

FEB./2013

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

K0300080

**LOW PRIORITY  
MAINTENANCE REQUIREMENTS**

**2014 KENOSHA POND MAINTENANCE REQUIREMENTS  
CITY OWNED/MAINTAINED**

#	POND NAME	3 acres or more?	WET/ DRY	DREDGING?	INLET/OUTLET IMPROVEMENTS?	VEGETATION REMOVAL?	REHABILITATION NEEDED	ESTIMATED COST	ENGINEERING & ADMINISTRATION	CONTINGENCIES	TOTAL COST FOR EACH POND	WORK PRIORITY	PRIORITY RANKING	TOTAL COST OF PROJECTS BY PRIORITY	YEARS TO COMPLETION WITH \$100,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$200,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$300,000 ANNUAL BUDGET <sup>1</sup>
25	Petretti	Yes	Wet & Dry		Yes		Reattach 15" pipe. Clean sediment from concrete gutters.	\$1,000 \$2,000	\$360	\$504	\$3,864	Low	3	\$19,320	1.9	1.0	0.6
22	Business Park A	Yes	Dry			Yes	Clear debris from structures. Clear willow brush. Clean channel.	\$1,000 \$2,000 \$2,000	\$600	\$840	\$6,440	Low	5				
36	Hillside	Yes	Wet			Yes	Clear vegetation from outlet structure. Clean channels.	\$1,000 \$2,000	\$360	\$504	\$3,864	Low	8				
29	Whitecaps D		Dry		Yes		Clear debris from outlet structure.	\$1,000	\$120	\$168	\$1,288	Low	11				
30	Whitecaps C		Dry		Yes		Clear debris from outlet structure.	\$1,000	\$120	\$168	\$1,288	Low	12				
37	St. Peter's	Yes	Wet			Yes	Clear debris and vegetation from structures.	\$2,000	\$240	\$336	\$2,576	Low	14				

NOTES:  
1. Assumes 50% of budget to high-priority projects, 40% to medium-priority projects, and 10% to low-priority projects.

Ponds Owned and Maintained  
by City of Kenosha  
Petretti



September 5, 2013

### Measurement Results for Petretti Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Inspection
N/A	N/A	4.8	2018

### Notes


1. The original design plans for the pond were not available. This dry pond had 4.8 feet of water in the north end in June of 2013.
2. The inlet and outlet structures were inspected and were found to be in good condition. The 15-inch pipe was starting to separate.
3. There is some sediment build-up in the concrete gutters.
4. The pond area had been mowed, but not recently.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will indicate whether sediment is accumulating in the small wet portion of the pond.
2. The concrete gutters should be cleaned.
3. Reattach 15-inch pipe.







6/18/13 Sunny 60° A7, dL4

PETRETTI

# 16200 - 10437


NO L in BSC ✓

MAINT  
CLEAN WATER'S

(91)

19<sup>th</sup> ST

A  
N





**NORTH POINTE**

WATER ELEV.=610.2

DEPTHS BELOW WATER

4.8 (TOP SEDIMENT)  
- (BOTTOM)

WATER SURFACE AREA = 392 SF



**Clark Dietz**  
ENGINEERS

K0300080

JUNE/2013

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

**Ponds Owned and Maintained  
by City of Kenosha  
Business Park A**



July 11, 2013

### Measurement Results for Business Park Basin A Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Inspection
1994	NA	NA	2018

### Notes

1. This dry bottom pond was inspected in February of 2013.
2. The inlets and outlets were inspected and were found to be in good structural condition.
3. Grass clippings were completely covering some of the structures.
4. The whole pond area was mowed, with some willow brush. The low end of the concrete channel was covered in muck.

### RECOMMENDATIONS

1. The pond should be inspected again in 2018.
2. Remove grass clippings from the inlet and outlet structures after mowing.
3. Clear willow brush as necessary.







2-13-2013 - WEDNESDAY

BUSINESS PARK KENDUSHA - BASIN 'A'

BB, TEMP: 35° F, SUNNY

START: 07:30 END: 4:00 PM

SQUARE INTAKE GRATE: (H)

5'0" x 5'0" ORL

INVERT: -2.8

(E) REP (24") → -2.9'


\* ALL STAKES TAKEN WITH (+) SHOULD BE (-) FOR CURVES!

✓ ALL LINE WORK STOPPED @ SQ GRATE.

CONTINUE SHOOTING TEL, TOE, AND GCI

ALL (GCI) NORTH OF NE/SE RUNNING

PATCH:



~~END @ 3700~~

- 2/21/2013 - THURSDAY BB


TEMP: 25° F

START: 7:00 END: 10:00

END @ 3010 → 3700

N1

01



18 PES  
3000

MAIN

\* BASS CLIPPINGS ON GRATES


\* SOME (LOW END) COVERED IN MUCK

\* know SLUD

KENOSHA BUSINESS PARK – BASIN A

DRY BOTTOM

52ND STREET



PRIMARY OUTLET STRUCTURE  
5'x5' CONC. BOX (SPILL-IN)  
IN-SPILL ELEV.=694.9  
(2) 4"Ø ORIFICE HOLES  
EACH SIDE @ 692.4  
OUTLET 24" RCP @ 692.1

CONC. SPILLWAY  
CREST=696.9

SECONDARY OUTLET STRUCTURE  
5'x5' CONC. BOX (SPILL-IN)  
IN-SPILL ELEV.=695.8  
OUTLET 24" RCP @ 692.9


CONC. CHANNEL  
(TYPICAL)

IE=696.0  
48x76" RCP  
(80" EQUIV.)

IE=696.0  
57x90" RCP  
(72" EQUIV.)

IE=696.0  
18" RCP  
END SECTION

88TH AVE



FEB./2013

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

**Clark Dietz**  
ENGINEERS

K0300080

**Ponds Owned and Maintained  
by City of Kenosha  
Hillside**



September 5, 2013

### Measurement Results for Hillside Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2005	4.5	4.2 – 5.2	2018

### Notes

1. The designed water depth of the pond is 4.5 feet. The measured water depth in July of 2013 varied between 4.2 and 5.2 feet.
2. The inlet and outlet structures were inspected and were found to be in good condition. There was some vegetation growing around the outlet structure.
3. Sediment build-up varied between 0.4 and 0.8 feet.
4. Sections of the pond perimeter had been mowed, with the grass left longer near the pond. The rip-rap area was clear.
5. Some sediment has built up in the concrete gutters.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. The concrete gutters should be cleaned.
3. Vegetation should be cleared around the outlet structure.







# HILLSIDE




WATER ELEV.= 664.2

DEPTHS BELOW WATER

4.8 (TOP SEDIMENT)

5.6 (BOTTOM)

WATER SURFACE AREA = 626,467 SF



JUNE/2013

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

**Clark Dietz**  
ENGINEERS

K0300080

**Ponds Owned and Maintained  
by City of Kenosha  
Whitecaps D**



July 10, 2013

### Measurement Results for WhiteCaps D Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1992	NA	NA	NA

### Notes

1. This dry pond was inspected in February of 2013.
2. The inlet and outlet pipes were inspected and were found to be in good structural condition.
3. Leaves and debris were built-up in front of the outlet grate to a height of about 3 feet.
4. The entire pond area is mowed.

### RECOMMENDATIONS

1. Remove debris from the outlet grate periodically to prevent back-ups.









2/25/13 20° sunny


WHITE CAPS BASIN D<sub>1</sub>

LAYER OF ICE 3" ± E SNOW  
AND BUREY THICK

OC # 4501 BS # 4500  
HR = 4.50

- RESTRICTED SIZE (?) ICE IN
- LOT OF LEAVES & DEBRIS PACKED AGAINST OUTLET LEAD TO ± 3' HIGH CAUSEWAY BACK UPS

— COME BACK FOR RESTRICTED SIZE (12" x 2") - 4.4'





Ponds Owned and Maintained  
by City of Kenosha  
Whitecaps C



July 10, 2013

### Measurement Results for WhiteCaps C Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1992	NA	NA	NA

### Notes

1. This dry pond only had scattered puddles when inspected in Spring of 2013.
2. The inlet and outlet pipes were inspected and were found to be in good structural condition.
3. Leaves and debris were clogging a portion of the outlet grate.
4. The entire pond is mowed.

### RECOMMENDATIONS

1. The pond should be maintained to keep the outlet opening clear.









2/26/13 AT-188-31° cloudy/windy

WHITE CARS BASIN C


6700

\* LIQUID MAINTENANCE

- RESTRICTOR ORIFICE (2" to 2.5")
- I.F.E. OUTLET PIPE
- TO TOP 2" ORIF. O.FLOW



- OUTLET LEAKAGE 6" UNITS PACKED LEAKAGE
- DRAINAGE CASSETTE WITH OUTLET

(25)




**WHITECAPS - BASIN C**

DRY BOTTOM



**OUTLET STRUCTURE**



Ponds Owned and Maintained  
by City of Kenosha  
St. Peter's



October 1, 2013

### Measurement Results for St. Peters Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1997	12	7.2 – 11.0	2018


### Notes

1. The designed water depth of the pond is 12 feet. The measured water depth in June of 2013 varied between 7.2 and 11.0 feet. We conclude that the pond is filling with sediment.
2. The inlet and outlet pipes were inspected and were found to be in good structural condition. Some debris was built up on the structures.
3. Sediment build-up averaged 1.1 feet.
4. Vegetation is growing in the spillway and structures. The pond perimeter had not been mowed recently.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. Clear vegetation and debris from the inlet and outlet structures.









Maintenance

- Clearing debris buildup on CB's
- Vegetation growth in concrete spillway

ST PETERS

• 6/21/13 Cloudy 75°  
 Started 7:30 - 11:40 A.M.

Shots 17000 - 17597

Diameter 46"  
 water level 57"  
 system of struct. 7'  
 water flow  
 could not see pipes in/out

CB1 -

Diameter 46"  
 water level 122"  
 bottom struct 137"  
 water flowing  
 could not see pipes  
 15" Diameter leaving


CB2 -

STP




DEPTH	0-20-13
17000	7.2, 8.2
	9.5, 10.7
	9.7, 10.4
	9.6, 9.6
	9.0, 10.0
	11, 12
17007	9.3, 9.5

End at 17598



CONC. CARBIDE SPILLWAY

side view



**ST PETERS**


**WATER ELEV. = 619.8**

**DEPTHS BELOW WATER**



9.0 (TOP SEDIMENT)

10.0 (BOTTOM)

**WATER SURFACE AREA = 1,041,280 SF**



**OUTLET STRUCTURE**



**Clark Dietz**  
ENGINEERS

K0300080

JUNE/2013

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

NO MAINTENANCE REQUIREMENTS

**2014 KENOSHA POND MAINTENANCE REQUIREMENTS  
CITY OWNED/MAINTAINED**

#	POND NAME	3 acres or more?	WET/ DRY	DREDGING?	INLET/OUTLET IMPROVEMENTS?	VEGETATION REMOVAL?	REHABILITATION NEEDED	ESTIMATED COST	ENGINEERING & ADMINISTRATION	CONTINGENCIES	TOTAL COST FOR EACH POND	WORK PRIORITY	PRIORITY RANKING	TOTAL COST OF PROJECTS BY PRIORITY	YEARS TO COMPLETION WITH \$100,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$200,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$300,000 ANNUAL BUDGET <sup>1</sup>
41	Whitecaps G		Wet				None.				N/A						

NOTES:

1. Assumes 50% of budget to high-priority projects, 40% to medium-priority projects, and 10% to low-priority projects.

**Ponds Owned and Maintained  
by City of Kenosha  
Whitecaps G**



July 10, 2013

### Measurement Results for WhiteCaps G Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1992	5.75	5.6 – 6.2	2018

### Notes

1. The designed water depth of the pond is 5.75 feet. The measured water depth in June of 2013 varied between 5.6 and 6.2 feet. We conclude that the pond was over-excavated at the time of construction.
2. The inlet and outlet pipes were inspected and were found to be in good structural condition.
3. Sediment build-up varied between 0 and 0.3 feet.
4. The whole pond perimeter is mowed.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. When mowing, leave a grassy strip around the pond perimeter to improve safety and deter geese.






2/25/13 WHITE CAPS POWO 6

- # 5000 →
- WIRED #4552 TO SPAD'S
- NEED - EDGE WATER
- SOUNDINGS
- ~~PIPE STAIR (MIN. CORNER)~~ 10'
- INU OF EAST END F.I.B.'S

MAINT.

• NAME


- 6-27-13 ESC
  - 5112 - 6.2, 6.5
  - 13 - 6.1, 6.3
  - 14 - 6.1, 6.3
  - 15 - 5.4, 5.8
  - 16 - 6.1, 6.2
  - 17 - 6.2, 6.2
  - 5118 - 5.1, 5.1
- EDGE OF WATER






**WHITECAPS BASIN G**

WATER ELEV. = 718.8

DEPTHS BELOW WATER



WATER SURFACE AREA = 48,093 SF




**Clark Dietz**  
 ENGINEERS

FEB./2013  
 5017 GREEN BAY ROAD  
 SUITE 126  
 KENOSHA, WI 53144  
 PHONE : 262.657.1550  
 FAX : 262.657.1594

K0300080

**PONDS OWNED AND MAINTAINED  
BY PRIVATE OWNER**

**HIGH PRIORITY  
MAINTENANCE REQUIREMENTS**

**2014 KENOSHA POND MAINTENANCE REQUIREMENTS  
PRIVATELY OWNED WITH MAINTENANCE AGREEMENT**

#	POND NAME	3 acres or more?	WET/ DRY	DREDGING?	INLET/OUTLET IMPROVEMENTS?	VEGETATION REMOVAL?	REHABILITATION NEEDED	ESTIMATED COST	ENGINEERING & ADMINISTRATION	CONTINGENCIES	TOTAL COST FOR EACH POND	WORK PRIORITY	PRIORITY RANKING	TOTAL COST OF PROJECTS BY PRIORITY	YEARS TO COMPLETION WITH \$100,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$200,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$300,000 ANNUAL BUDGET <sup>1</sup>
49	Gateway		Wet	Yes	Yes	Yes	Dredge to remove sediment and restore depth.	\$16,000	\$3,240	\$4,536	\$34,776	High	3	\$360,640	7.2	3.6	2.4
							Inspect functionality of inlet pipe and make necessary repairs.	\$5,000									
							Attach outlet pipe to structure.	\$1,000									
							Clear vegetation from structures and perimeter.	\$5,000									
56	Heritage Heights 2		Wet	Yes	Yes		Dredge to remove sediment and restore depth.	\$13,000	\$2,160	\$3,024	\$23,184	High	4	\$360,640	7.2	3.6	2.4
							Inspect inlet pipe and outlet structures and clear clogs.	\$5,000									
14	Menards	Yes	Wet	Yes	Yes	Yes	Remove vegetation around perimeter and structures.	\$2,000	\$19,920	\$27,888	\$213,808	High	7	\$360,640	7.2	3.6	2.4
							Clean all structures.	\$1,000									
							Install grates on 2 inlets.	\$1,000									
							Dredge pond to remove sediment.	\$162,000									
20	South Port Plaza Basin A	Yes	Wet	Yes			Dredge to remove sediment.	\$68,000	\$8,160	\$11,424	\$87,584	High	8				
10	LeMay Buick		Wet		Yes		Clean trash from structures.	\$1,000	\$120	\$168	\$1,288	High	9				

NOTES:  
1. Assumes 50% of budget to high-priority projects, 40% to medium-priority projects, and 10% to low-priority projects.

Ponds Owned and Maintained  
By Private Owner  
Gateway



October 31, 2013

### Measurement Results for Gateway Subdivision Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
N/A	N/A	0 – 0.3	2018

### Notes

1. The original design plans for the pond were not available. The measured water depth in March of 2013 was 0 at the west end of the pond and 0.3 feet at the east end. The pond is full of sediment.
2. The inlet pipe was dry and may no longer be functional.
3. Sediment build-up averaged between 0.8 and 1.1 feet.
4. The entire pond is full of cattails. Willow shrubs have grown up around the east and south sides of the pond. Vegetation is also growing in and around the inlet and outlet structures.
5. The outlet structure has separated from the adjacent pipe.
6. A possible emergency outflow is located at the southeast corner.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. The outlet structure should be repaired and reattached to the adjacent pipe.
3. The pond should be dredged to its original design depth.
4. The cattails and willows should be cleared, especially from the structures.
5. Further investigation is necessary to determine if the inlet pipe is functional or in need of repair.









# GATEWAY



WATER ELEV.= 679.1

DEPTHS BELOW WATER

0.0 (TOP SEDIMENT)

0.0 (BOTTOM)

WATER SURFACE AREA = 6,300 SF



APR./2013

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

**Clark Dietz**  
ENGINEERS

K0300080

Ponds Owned and Maintained  
By Private Owner  
Heritage Heights 2



October 30, 2013

### Measurement Results for Heritage Heights 2 Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2005	4	0.9 – 1.7	2018

### Notes

1. The designed water depth of the pond is 4 feet. The measured water depth in October of 2013 varied between 0.9 and 1.7 feet. The pond is apparently filling with sediment.
2. The inlet and outlet structures were inspected and are not functioning. The water level in the pond is above the elevation of the structures. Water is covering the outlet grate and stagnant water is sitting in the outlet structure.
3. Sediment build-up varied between 0.3 and 1.3 feet.
4. The pond perimeter has been mowed.
5. Water in the pond is stagnant and partially covered with surface vegetation. Stems from old vegetation remain in the water.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. There is heavy sediment buildup in the pond. It should be dredged to its original design depth.
3. If dredging does not restore the operation of the inlet and outlet structures, further investigation is needed to determine the cause of the problem.
4. The pond perimeter should be mowed to within a foot of the water.










**SITING HERITAGE HTS  
Retention Basin #2**

8/23/13  
SURVEY: LOWE  
SHOTS 20000 - 20193; 20194-20200

Maintenance Plan

- Overflows not working. Water does not recede or leave pan
- Water elevation above outlet locations
- Stagnant
- HEAVILY SLOTTED SEDIMENTED



20195	0.5	0
20196	1.65	1.50
20197	1.60	2.20
20198	1.50	81
20199	1.50	2.10
20200	1.35	2.16

HERITAGE HEIGHTS - 2



WATER ELEV.= 733.5

DEPTHS BELOW WATER

1.4 (TOP SEDIMENT)

2.2 (BOTTOM)

WATER SURFACE AREA = 8,451 SF



AUG./2013

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

**Clark Dietz**  
ENGINEERS

K0300080

Ponds Owned and Maintained  
By Private Owner  
Menards



July 11, 2013

### Measurement Results for Menards Pond


Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1996	6	3.6 – 6.7	2018



### Notes


1. The designed water depth of the pond is 6 feet. The measured water depth in July of 2013 varied between 3.6 and 6.7 feet. We conclude that the pond was over-excavated at the time of construction but is now starting to fill up with sediment.
2. The inlet and outlet pipes were inspected and were found to be in good structural condition. Two of the inlets do not have grates.
3. Sediment build-up varied between 0 and 1.3 feet.
4. There is thick vegetation growth all around the pond perimeter.
5. Vegetation is also growing in the rip-rap near the pond inlets and outlets.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. The trees and vegetation growing around the pond should be cleared, especially near the rip-rap, inlets, and outlet.
3. The outlet structure requires a good cleaning, and the two inlets at the south end should be cleared.
4. Perform routine mowing.
5. Perform dredging operations at the pond to restore it to its design depth.













4-4-13 Sunday 30°


ATT+B

**MENARDS**

STACK # 10400 - FWD 10560

7-2-13	T/WIR
30,013	- 3.6, 3.9
	4.3, 4.8
	4.5, 4.7
	4.0 -
	4.2, 5.1
	5.0, 5.6
	6.7, 8.0
	5.7, 6.0
	5.0, 0
30,022	4.4, -

- \* TOWER CLEAR WITHIN PERIMETER
- \* BOT. BAY OF OUTLET - GOOD CLEARING
- \* OUTLET CLEAN W/ & BEST IN



**MENARDS**

WATER ELEV.= 684.2

DEPTHS BELOW WATER

0.0 (TOP SEDIMENT)

0.0 (BOTTOM)

WATER SURFACE AREA = 229,951 SF

36"X60" RCP  
END SECTION  
IE=684.1

MH  
(FRAME NOT  
ON OPENING)

"PAVER" RIP-RAP

CONC. SPILLWAY  
CREST=688.1


OVERFLOW

12" ADS TILE

**OUTLET STRUCTURE (3 BAY)**

- 4.5'x6' GRATED OPNG I.E. ● 683.9
- 8"Ø ORIFICE ● 683.9
- 8'x6' GRATED OPNG IN-SPILL ● 685.1
- 12"Ø ORIFICE ● 683.8
- 5'x6' GRATED OPNG IN-SPILL ● 687.1
- 27" RCP OUTLET ● 683.7

RAILROAD




**OUTLET STRUCTURE**

**MENARDS**

42" RCP  
END SECTION  
IE=684.1

74"X48" RCP  
END SECTION  
IE=683.7



FEB./2013

**Clark Dietz**  
ENGINEERS

K0300080

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

**Ponds Owned and Maintained  
By Private Owner  
South Port Plaza Basin A**



July 11, 2013

### Measurement Results for South Port Plaza Basin A Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2000	3.6 (west), 5.6 (east)	1.0 – 5.4	2018


### Notes

1. The designed water depth of the pond is 3.6 feet on the west side of the pond and 5.6 feet on the east side of the pond. The measured water depth in July of 2013 varied between 1.0 and 5.4 feet. We conclude that the pond has partially filled with sediment.
2. The inlet and outlet pipes were inspected and were found to be in good structural condition.
3. Sediment build-up varied between 0 and 1.8 feet.
4. The entire pond perimeter is mowed.
5. The water was murky and stagnant.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. When mowing, leave a grassy strip around the perimeter of the pond to deter geese.
3. Perform dredging operations at the pond to restore it to its design depth.







19

4-5-13 5:45 AM

AT, BB

START # 11900 → 12232

SOUTHERT PLAZA EAST

7-2-13 5:45 AM

304007 - 3.7, 5.1

0 - 3.4, 4.9

1 - 1.0, 1.7

10 - 4.3, 5.9



11 - 5.4, 6.8

304012 3.7, 5.5

(MURKIN, STRANGE)

• LUSOR SHAPE

LAUREN BAY RD



CASH SPENDING

574 575



Access RD

LOT SEPARATED

EST. WALL


# SOUTHPORT PLAZA BASIN A

WATER ELEV.  
695.7


## DEPTHS BELOW WATER

0.0 (TOP SEDIMENT)  
⊕  
0.0 (BOTTOM)

WATER SURFACE AREA = 47,043 SF



OUTLET STRUCTURE



OUTLET STRUCTURE  
2.5'x5.5' BOT BAY @ 695.7  
8" ORIFICE @ 695.6  
IN-SPILL WALL (TOP=697.6)  
2.5'x2.5' TOP BAY @ 699.1  
OUTLET 12" RCP @ 695.5

IE=695.9  
36" RCP  
END SECTION

IE=695.7  
21" RCP  
END SECTION

CONC. SPILLWAY  
CREST=702.2

IE=700.6  
24"x36"  
ELLIP. RCP  
END SECTION



**Clark Dietz**  
ENGINEERS

FEB./2013

K0300080

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

Ponds Owned and Maintained  
By Private Owner  
Lemay Buick



July 11, 2013

### Measurement Results for LeMay Buick Pond


Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
N/A	N/A	5.9 – 6.2	2018

### Notes

1. The original design plans for the pond were not available. The measured water depth in July of 2013 varied between 5.9 and 6.2 feet.
2. The inlet and outlet pipes were inspected and were found to be in good structural condition. A new inlet has been installed on the north side of the pond.
3. The 24" inlet was clogged with trash and there was also trash on the outlet structure.
4. Sediment build-up varied between 0.8 and 1.3 feet.
5. The pond area has been mowed.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. The trash should be cleaned from the inlet and outlet.
3. Routine clean-up should be performed around the pond.







4-2-3 Sun Y 40

LEMA (NO OWNED BY P

START # 1020

END # 10298

1310 ROLX

RE COG E BA UP P NO

X C O T ET T TUE

4x →

4x

4x4

4x6

4x6


4x6

4x6

3' OF 105

4x6

4x6



TICKETS  
ALWAYS  
CLEANING

4 CHAMBERS  
SEE DETAIL

RIPRAT

ROCKS

24  
RIP

(CLOSED)  
HATCHWAY  
GATE



**LEMAY BUICK**

WATER ELEV.  
688.7


DEPTHS BELOW WATER

0.0 (TOP SEDIMENT)  
⊕  
0.0 (BOTTOM)

WATER SURFACE AREA = 11610 SF



- OUTLET STRUCTURE (4 BAY)**
- 4'x8' LOWER GRATED OPENING I.E. @ 688.7
  - 3"Ø ORIFICE @ 689.1
  - 4'x4' GRATED OPENING IN-SPILL @ 690.6
  - 12"Ø ORIFICE @ 688.5
  - 4'x8' GRATED OPENING IN-SPILL @ 691.6
  - 15"Ø ORIFICE @ 688.8
  - 4'x8' GRATED OPENING IN-SPILL @ 693.6
  - 36" RCP OUTLET @ 688.4





**Clark Dietz**  
ENGINEERS

APR./2013

K0300080

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

MEDIUM PRIORITY  
MAINTENANCE REQUIREMENTS

**2014 KENOSHA POND MAINTENANCE REQUIREMENTS  
PRIVATELY OWNED WITH MAINTENANCE AGREEMENT**

#	POND NAME	3 acres or more?	WET/DRY	DREDGING?	INLET/OUTLET IMPROVEMENTS?	VEGETATION REMOVAL?	REHABILITATION NEEDED	ESTIMATED COST	ENGINEERING & ADMINISTRATION	CONTINGENCIES	TOTAL COST FOR EACH POND	WORK PRIORITY	PRIORITY RANKING	TOTAL COST OF PROJECTS BY PRIORITY	YEARS TO COMPLETION WITH \$100,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$200,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$300,000 ANNUAL BUDGET <sup>1</sup>
15	Midwest Transportation	Yes	Wet		Yes	Yes	Replace grate on outlet structure. Remove brush at north end and near 72" inlet.	\$1,000 \$2,000	\$360	\$504	\$3,864	Medium	1	\$926,072	23.2	11.6	7.7
47	Bradford Estates		Wet	Monitor	Yes		Bolt down loose grates on outlet structure. Clean grates on structures. Monitor need for dredging within next five years.	\$1,000 \$1,000 \$6,000	\$960	\$1,344	\$10,304	Medium	3				
1	Ansari (Barth Storage)		Wet		Yes	Yes	Replace bottom grate on outlet. Reattach end section on 60" inlet. Remove vegetation from rip-rap.	\$1,000 \$1,000 \$2,000	\$480	\$672	\$5,152	Medium	4				
6	Palmen Motors		Wet		Yes	Yes	Construct swale to nearby culvert to remedy drainage problem. Clear trees around outlet and spillway.	\$15,000 \$1,000	\$1,920	\$2,688	\$20,608	Medium	6				
5	Prairie Lake Estates (Heiberg)	Yes	Wet		Yes	Yes	Clean structures and remove vegetation from rip-rap. Inspect downstream channel for clogging.	\$2,000 \$1,000	\$360	\$504	\$3,864	Medium	7				
50	Hunters Ridge A		Wet		Yes	Yes	Clean pipe at southeast corner to remove clog. Clear vegetation from structures and pond perimeter.	\$2,000 \$5,000	\$840	\$1,176	\$9,016	Medium	11				
52	Hunters Ridge C		Wet		Yes	Yes	Reattach inlet pipe. Repair two eroded channels. Clear vegetation from structures and pond perimeter.	\$1,000 \$5,000 \$5,000	\$1,320	\$1,848	\$14,168	Medium	12				
51	Hunters Ridge B		Wet		Yes	Yes	Reattach end sections to inlet pipes. Clear vegetation from structures and pond perimeter. Inspect structures to determine cause of low water level.	\$2,000 \$5,000 \$5,000	\$1,440	\$2,016	\$15,456	Medium	13				
46	Woodman's Basin B		Wet		Yes	Yes	Clear vegetation from outlet structure and perimeter. Clean outlet to remove clog; note if water level drops. Clear pond area of debris.	\$5,000 \$5,000 \$1,000	\$1,320	\$1,848	\$14,168	Medium	14				
45	Woodman's Basin A		Wet	Yes		Yes	Dredge at south end and near outlet structure. Clear vegetation from structures and perimeter. Clear pond area of debris.	\$36,000 \$5,000 \$1,000	\$5,040	\$7,056	\$54,096	Medium	15				
43	Indian Trail Estates - YMCA	Yes	Wet		Yes	Yes	Clear vegetation from structures, rip-rap, and pond perimeter. Repair washed-out rip-rap.	\$5,000 \$2,000	\$840	\$1,176	\$9,016	Medium	19				
12	Leona's Rolling Meadows Subdivision C1		Wet	Yes		Yes	Dredge to remove sediment. Clear vegetation around pond.	\$23,000 \$2,000	\$3,000	\$4,200	\$32,200	Medium	20				
11	Leona's Rolling Meadows Subdivision C	Yes	Wet	Yes	Yes		Dredge to remove sediment. Clean outlet periodically.	\$133,000 \$1,000	\$16,080	\$22,512	\$172,592	Medium	21				
9	KM Property Owners South Port Plaza B		Wet	Monitor	Yes		Sediment is deep in some areas; monitor need for dredging over next five years. Clean outlet and check for blockage.	\$31,000 \$5,000	\$4,320	\$6,048	\$46,368	Medium	23				
53	Mahone	Yes	Wet	Monitor		Yes	Clear vegetation from structures, rip-rap, and north end of pond. Determine design depth of pond and whether dredging is necessary. Monitor need for dredging within next five years.	\$2,000 \$1,000 \$393,000	\$47,520	\$66,528	\$510,048	Medium	25				
2	Dairyland Greyhound Park (WEST)		Wet			Yes	Remove perimeter vegetation and locate structures.	\$2,000	\$240	\$336	\$2,576	Medium	26				
3	Dairyland Greyhound Park (NORTH)	Yes	Wet			Yes	Remove vegetation around perimeter and outlet structure.	\$2,000	\$240	\$336	\$2,576	Medium	27				

NOTES:  
1. Assumes 50% of budget to high-priority projects, 40% to medium-priority projects, and 10% to low-priority projects.

Ponds Owned and Maintained  
By Private Owner  
Midwest Transportation



July 10, 2013

### Measurement Results for Midwest Transportation Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1999	4	3 – 5.3	2018


### Notes


1. The designed water depth of the pond is 4 feet. The measured water depth in April of 2013 varied between 3 and 5.3 feet. We conclude that the pond was over-excavated at the time of construction and is starting to fill with sediment in one small area.
2. The inlet and outlet pipes were inspected. They are in good condition except that the bottom grate of the outlet structure is missing.
3. Sediment build-up varied between 0 and 0.4 feet.
4. The area around the pond perimeter is grassy. The only heavy vegetation growth is at the north end and near the 72" pipe.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. Clear the willow brush at the north end and surrounding the 72" pipe.
3. Replace the bottom grate on the outlet structure.









4-2-73 SUNNY 40°  
AT BE

MIDWINTER TRANSPORTATION

START # 9600 - 9759  
DEPTS 9760 → 9770


MAINTENANCE - CUT SCATTERED WILLOW BRUSH  
MAINLY N. END & AT 72" PIPE

- NEED LOW WALL BENCH
- NEED B/W DEPTS



7/4" WIRE HO. 5" (W)

7-1-113	9760 - 3.57.0	1 44.1
	NWX 412 7.5	62 54.02
	63 46.49	64 41.5
	65 47.1	66 46.1
	67 44.48	SEX 68 47.4
	69 46	70 46
	71 53.51	
	72 46	



MIDWEST TRANSPORTATION

DEPTHS BELOW WATER

- 0.0 (TOP SEDIMENT)
- 0.0 (BOTTOM)

WATER SURFACE AREA = 406,182 SF

CONC. SPILLWAY  
CREST=690.3

60TH ST


RIP-RAP

OVERFLOW

OUTLET STRUCTURE  
2-BAYS. UPPER GRATED, LOW GRATE MISSING  
TOP 4.5'X10', LOWER 4.5'X3'  
LOWER BAY WALL (TOP=676.5)  
18"W X 9"H OPENING @ 675.5  
TOP WALL @ 679.9  
OUTLET 42" RCP PIPE @ 675.3

IE=673.4  
72" RCP

WATER ELEV.  
676.0




OUTLET STRUCTURE

RAILROAD

IE=676.4  
42" RCP  
END SECTION

IE=675.7  
18" CMP



**Clark Dietz**  
ENGINEERS

APR./2013

K0300080

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

Ponds Owned and Maintained  
By Private Owner  
Midwest Transportation



September 5, 2013

**Measurement Results for Bradford Estates Pond**

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2003	4	3.5	2018

**Notes**

1. The designed water depth of the pond is 4 feet. The measured water depth in June of 2013 was approximately 3.5 feet. We conclude that the pond is starting to fill up with sediment.
2. The inlet and outlet pipes were inspected. There were loose grates on the outlet structure. There were also heavy grass clippings and plastic debris built up on the structures.
3. Sediment build-up averaged approximately 0.8 feet.
4. The whole pond perimeter had been mowed to the water's edge.

**RECOMMENDATIONS**

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. The loose grates should be bolted down.
3. The structure grates should be cleaned regularly.
4. The City should consider dredging this small pond within the next five years.
5. Do not mow a narrow strip around the pond to improve safety.







6/13/13 AT SUMMIT 250



BRADFORD ESTATES

STACT # 15600-15682

MANIFESTATION

- \* BOWL DOWN SS GRATE ON OUPFL FLOW
- \* " " METAL WATER OUTLET (LOWE)
- \* LUMBS CLIPPINGS? PLASTIC DEBRIS

7-2-13  
DEPTAS



**BRADFORD ESTATES**


WATER ELEV.= 613.4

DEPTHS BELOW WATER


3.6 (TOP SEDIMENT)

4.4 (BOTTOM)


WATER SURFACE AREA = 18,904 SF



**OUTLET STRUCTURE**



I, J  
P  
AND  
V




**Clark Dietz**  
 ENGINEERS

JUNE/2013  
 5017 GREEN BAY ROAD  
 SUITE 126  
 KENOSHA, WI 53144  
 PHONE : 262.657.1550  
 FAX : 262.657.1594

K0300080

Ponds Owned and Maintained  
By Private Owner  
Bradford Estates



September 5, 2013

**Measurement Results for Bradford Estates Pond**

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2003	4	3.5	2018

**Notes**

1. The designed water depth of the pond is 4 feet. The measured water depth in June of 2013 was approximately 3.5 feet. We conclude that the pond is starting to fill up with sediment.
2. The inlet and outlet pipes were inspected. There were loose grates on the outlet structure. There were also heavy grass clippings and plastic debris built up on the structures.
3. Sediment build-up averaged approximately 0.8 feet.
4. The whole pond perimeter had been mowed to the water's edge.

**RECOMMENDATIONS**

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. The loose grates should be bolted down.
3. The structure grates should be cleaned regularly.
4. The City should consider dredging this small pond within the next five years.
5. Do not mow a narrow strip around the pond to improve safety.










6/13/13 AT SUMMIT 25°

BRADFORD ESTATES

STACT # 15600-15682

MANIFESTATION

- \* BOWL DOWN SS GRATE ON OUPFL FLOW
- \* " " METAL WATER OUTLET (LOWE)
- \* LUMBS CLIPPINGS? PLASTIC DEBRIS



**BRADFORD ESTATES**


WATER ELEV.= 613.4

DEPTHS BELOW WATER


3.6 (TOP SEDIMENT)

4.4 (BOTTOM)


WATER SURFACE AREA = 18,904 SF



**OUTLET STRUCTURE**



I, J  
P  
AND  
V




**Clark Dietz**  
 ENGINEERS

JUNE/2013  
 5017 GREEN BAY ROAD  
 SUITE 126  
 KENOSHA, WI 53144  
 PHONE : 262.657.1550  
 FAX : 262.657.1594

K0300080

Ponds Owned and Maintained  
By Private Owner  
Ansari (Barth Storage)



July 12, 2013

### Measurement Results for Ansari (Barth Storage) Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2000	5.7	4.7 – 7.7	2018

### Notes


1. The designed water depth of the pond is 5.7 feet. The measured water depth in July of 2013 varied between 4.7 and 7.7 feet. We conclude that the pond was over-excavated at the time of construction.
2. The inlet and outlet pipes were inspected and were found to be in fair structural condition. The bottom grate of the outlet structure is rusty. The end section on the 60" inlet is separated from the pipe.
3. Sediment build-up ranged between 0.2 and 0.5 feet.
4. The whole pond area is mowed. Some weeds and saplings are growing in the rip-rap areas near the structures.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. The bottom grate of the outlet structure should be replaced.
3. Reattach the end section of the 60" inlet to the pipe.
4. When mowing, leave a grassy strip around the pond to deter geese and improve safety.








S-14-13 AT Sunny 75°


ANSSARI

# BOD → 13193




- \* CURVE SEPARATE E TWO SECTIONS
- \* NEW LOWER LEAVE E CURVE STRUCT.
- \* RE-ATTACH LD" FRS

7-2-13  
 30035 - 5.7, 6.0  
 4.7, 5.2  
 6.5, 6.7  
 5.7, 5.9  
 6.3, 6.8  
 7.7, 8.1





**ANSARI**  
 WATER ELEV. = 702.8  
 DEPTHS BELOW WATER  
 0.0 (TOP SEIOMENT)  
 0.0 (BOTTOM)  
 WATER SURFACE AREA = 91,668 SF



Ponds Owned and Maintained  
By Private Owner  
Palmen Motors



September 4, 2013

### Measurement Results for Palmen Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2001	2.5	3.9 – 5.0	2018

### Notes

1. The designed water depth of the pond is 2.5 feet. The measured water depth in June of 2013 varied between 3.9 and 5.0 feet. We conclude that the pond was over-excavated at the time of construction.
2. The outlet structure is not functioning properly. It is placed below the grade of the adjacent swamp.
3. No sediment build-up was measured in the pond.
4. The whole pond perimeter area is mowed. Trees are growing at the outlet structure and the concrete spillway.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. The trees around the outlet structure and spillway should be removed.
3. The drainage problem could be alleviated by dredging the swale to the railroad culvert approximately 50 feet away.







PALMEN


WATER ELEV.= 687.3

DEPTHS BELOW WATER


4.3 (TOP SEDIMENT)

4.3 (BOTTOM)


WATER SURFACE AREA = 32,201 SF



OUTLET STRUCTURE



- OUTLET STRUCTURE (3 BAY)
- 2'x3' LOWER GRATED OPENING I.E. @ 686.8
  - 3"Ø ORIFICE @ 686.8
  - 3'x3' GRATED OPENING IN-SPILL @ 687.8
  - 6"Ø ORIFICE @ 686.7
  - 3'x3' GRATED OPENING IN-SPILL @ 688.8
  - 9"Ø ORIFICE @ 687
  - TOP WALL @ 689.8
  - 12" RCP OUTLET @ 687



JUNE/2013

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

**Clark Dietz**  
ENGINEERS

K0300080

Ponds Owned and Maintained  
By Private Owner  
Prairie Estates (Heiberg)



July 16, 2013

### Measurement Results for Prairie Lake Estates Pond


Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1983	N/A	4.7 – 16.0	2018

### Notes


1. The designed water depth of the pond is unknown. The plans do not show the elevation of the outlet or the bottom of the pond. The measured water depth in July of 2013 varied widely between 4.7 and 16.0 feet.
2. The inlet and outlet structures were inspected and were found to be in fair condition.
3. Sediment build-up varied between 0 and 2.0 feet.
4. Portions of the pond perimeter are mowed to the water's edge. Cattails and brush have grown up around the edge in other areas. The rip-rap area near the outlet is heavily vegetated.
5. 0.9 feet of water was above the weir, indicating that the downstream channel might be clogged.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. The vegetation within the rip-rap and around the outlet should be cleared out and the structures cleaned of debris. The downstream channel should be checked for clogging or a possible obstruction.
3. When mowing, leave a grassy strip around the pond to deter geese and improve safety.
4. Light maintenance is required at the weir.











**PRAIRIE LAKE ESTATES (HEIBERG)**

WATER ELEV.  
679.9


DEPTHS BELOW WATER

0.0 (TOP SEDIMENT)  
0.0 (BOTTOM)

WATER SURFACE AREA = 339,620 SF



OUTLET STRUCTURE



APR./2013

**Clark Dietz**  
ENGINEERS

K0300080

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

Ponds Owned and Maintained  
By Private Owner  
Hunters Ridge A



January 15, 2014

### Measurement Results for Hunters Ridge Pond A

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1991	12	4 – 4.7	2018

### Notes

1. The designed water depth of the pond is believed to be 12 feet, similar to the other Hunters Ridge ponds. The design plans are not clear. The measured water depth in June of 2013 varied between 4 and 4.7. The pond was also inspected in December 2013.
2. The structures were inspected. The pipe at the southeast corner is clogged.
3. Sediment build-up averaged approximately 1.2 feet.
4. Thick brush surrounds the entire pond. Vegetation is also growing in and around the structures. The water was stagnant.


### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. The pipe at the southeast corner should be inspected and the clog cleared.
3. The vegetation around the pond should be cleared, especially from the structures.



Hunters Rise  
10-11 AM '78  
Over Cast

6-24-13




17700 W 235526.94 17701 N 235357.51  
E 2547772.17 E 2548104.13  
E 6 648.90 E 6 687.10

COUNTY 2283 - 133,000 AC 1 235415.408 E 25475571.959 612.250  
922,33,001 23.5 251.526 2548064.889 641.755

7-2-13  
30  
59  
112 -  
134,143  
91,104  
102,110.6  
108,114  
12,104  
129,10

CONTINUED ON  
Pg. 113

(97)



12-9-2012  
12-6-2013

BBB/JN

PARTLY  
SUNNY, 10°

HUNTERS RIDGE

TOPO - OC # 1, H1 = 5.51, BS # 2, ARS # 5  
START # 276  
35, 276  
END # 478  
35, 478

✓ 280 - ESC 24  
✓ 290 - \* SHOT ON (N) EDGE, MIDDLE OF GR. E

✓ 291 - ESM 24  
✓ 325 -   
✓ 330 -

~~332~~

✓ 332 - HND = 5.20,  5.20

✓ 349 - TB3!  
✓ 2/10/19 -

403 shot  while on top of pipe   
on bottom of FES (invert elev.)



~~408~~ 432. ESC 24

444  
443  
465  
476  
EW 3  
TOE 3  
TB 4  
TOE 4

HUNTERS RIDGE  
 WATER ELEV.= SEE PLAN  
 DEPTHS BELOW WATER

3.5 (TOP SEDIMENT)  
 ◆  
 4.4 (BOTTOM)

WATER SURFACE AREA = SEE PLAN



DEC./2013

5017 GREEN BAY ROAD  
 SUITE 126  
 KENOSHA, WI 53144  
 PHONE : 262.657.1550  
 FAX : 262.657.1594

**Clark Dietz**  
 ENGINEERS

K0300080

Ponds Owned and Maintained  
By Private Owner  
Hunters Ridge C



January 16, 2014

### Measurement Results for Hunters Ridge Pond C

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1991	12	9.1 – 13.6	2018

### Notes

1. The designed water depth of the pond is 12 feet. The measured water depth in July of 2013 varied between 9.1 and 13.6 feet. The pond was also inspected in December 2013.
2. The inlet and outlet structures were inspected. The end section on the inlet at the west end of the pond is separating from the pipe. Two channels on the north side of the pond are eroded.
3. Sediment build-up averaged between 0 and 1.3 feet.
4. Willow shrubs have grown up around most of the pond. Thick vegetation is also growing in and around the inlet and outlet structures.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. The inlet structure should be repaired and reattached to the adjacent pipe.
3. The eroded channels should be repaired.
4. The cattails and willows should be cleared, especially from the structures.











97



H  
10-11 AM 478  
Over Cast



17700 N 235526.94 17701 N 235354.51  
E 254772.17 E 2548104.13  
EL 646.90 EL 637.10

Charlottesville - 33000 05.1 235415.408 25479571.946 642.25  
P42 33.001 235251.550 2548064.589 641.755

7-2-13 35,000 →

59  
112 -  
134, 143  
91, 104  
122, 106  
108, 114  
12, 104  
129, 10

★ CONTINUED ON  
Pg. 93

12-9-2012

PAROLE SUPPLY, 10'

BBB/JN

HUNTERS RIDGE

TOPO - OC # 1, H1 = 5.5', BS # 2, HRS 475

START # 276  
35,276  
END # 478  
35,478

✓ 280 - ESC 24

✓ 290 - \* SHOT ON (N) EDGE, MIDDLE OF BR

✓ 291 - ESM 24

✓ 325 - ~~24~~

✓ 330 - ~~24~~

~~334~~

✓ 332 - HRC = 5.20, ~~24~~

✓ 349 - TB 3!

✓ 21079 - ~~24~~

403 shot ~~24~~ where top of pipe ~~24~~ opens on bottom of FES (invert elev.)

~~432~~ ESC 24

444 EW 3

443 TOE 3

465 TB 4

476 TOE 4


HUNTERS RIDGE  
 WATER ELEV.= SEE PLAN

DEPTHS BELOW WATER

3.5 (TOP SEDIMENT)

4.4 (BOTTOM)

WATER SURFACE AREA = SEE PLAN



DEC./2013

**Clark Dietz**  
 ENGINEERS

K0300080

5017 GREEN BAY ROAD  
 SUITE 126  
 KENOSHA, WI 53144  
 PHONE : 262.657.1550  
 FAX : 262.657.1594

Ponds Owned and Maintained  
By Private Owner  
Hunter Ridge B



January 16, 2014

### Measurement Results for Hunters Ridge Pond B

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1991	12	10.4	2018

### Notes


1. The designed water depth of the pond is 12 feet. The measured water depth in July of 2013 was approximately 10.4 feet.
2. The inlet and outlet structures were inspected. The end sections on the two inlets on the north end of the pond and the one on the outlet at the south end of the pond are all separating from the pipes.
3. Sediment build-up averaged approximately 0.5 feet.
4. Willow shrubs and trees are growing around most of the pond. Vegetation is also growing in and around the inlet and outlet structures, especially the inlet on the east side of the pond.
5. The measured water elevation is lower than the design elevation.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. All the separating end sections should be repaired and reattached to the adjacent pipes.
3. The willows and trees should be cleared, especially from the structures.
4. The function of the inlets and outlet should be checked to determine the cause of the low water level.








H  
10-11 AM 78°  
Over Cast

6-24-13



1770 W 235526.94 1770 N 235357.51  
 E 254772.17 E 2548104.13  
 EL 648.90 EL 637.10

02233001 235415.408 2547557.94 E 648.256  
 02233001 235251.550 2548064.989 641.755

35,000 →

7-2-13  
~~30~~ 59 - 9.2, 10.2

11.2 -  
 13.4, 14.3  
 9.1, 10.4  
 10.0, 10.6  
 10.8, 11.4  
 12.1, 12.4  
 12.9, 13.0

\* CONTINUED ON  
 Pg. 113

12-9-2012

12-6-2013

BRE/JN

PACIFIC SUPPLY, INC.

HUNTERS RIDGE

TOPO - OC # 1, H1 = 5.51, BS # 2, HRS 3.5

START # 276 END # 478

351276

35,478

✓ 280 - ESC 24 \* SHOT ON (N) EDGE, MIDDLE OF BR

✓ 291 - ESM 24

✓ 325 - ~~24~~

✓ 330 - ~~24~~

~~331~~

✓ 332 - HIR = 5.20, 5.20

✓ 349 - TB3!

✓ 349 - TB3!

✓ 349 - TB3!

403 shot ~~24~~ when top of pipe ~~24~~ opens on bottom of FES (invert elev.)

~~432~~ ESC 24

444 EW 3

443 TOE 3


465 TB 4

476 TOE 4

HUNTERS RIDGE  
 WATER ELEV.= SEE PLAN  
 DEPTHS BELOW WATER

3.5 (TOP SEDIMENT)  
 4.4 (BOTTOM)

WATER SURFACE AREA = SEE PLAN



DEC./2013

5017 GREEN BAY ROAD  
 SUITE 126  
 KENOSHA, WI 53144  
 PHONE : 262.657.1550  
 FAX : 262.657.1594

**Clark Dietz**  
 ENGINEERS  
 K0300080

Ponds Owned and Maintained  
By Private Owner  
Woodman' s Basin B



July 11, 2013

### Measurement Results for Woodmans Basin B Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1995	4	4.8 – 5.4	2018

### Notes

1. The designed water depth of the pond is 4 feet; the design plans are not clear. The measured water depth in June of 2013 varied between 4.8 and 5.4 feet.
2. The inlet and outlet pipes were inspected and were found to be in good structural condition.
3. Sediment build-up varied between 0.4 and 1.1 feet.
4. Vegetation has grown up around the outlets and certain other areas of the pond.
5. The water level was high, indicating that the outlet might be plugged.
6. The water was cloudy, likely due to the nearby construction.

### RECOMMENDATIONS


1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. The vegetation should be cleared, especially around the outlets.
3. The outlet structure should be cleaned to remove a possible blockage.
4. Perform routine mowing, maintenance, and clean-up at the pond.







(M)



3-28-3

SUNNY

WOODMAN'S BASIN "B"

START @ # 7600

- \* LIGHT MAINTENANCE
- \* CLEAN UP OUTLET
- \* TRIM WILLOW SCRUB

U-27-1	
7181	54,015 * WRE ALI#(are - PUBLISHED?)
82	50,516
83	53,517
7184	18,517

\* CHAIN ARE TO NEW  
CONSTRUCTION AREA BY

WRE #2 = 6896.3

# WOODMANS - BASIN B



WATER ELEV.=686.3

DEPTHS BELOW WATER

- ◆ 0.0 (TOP SEDIMENT)
- ◆ 0.0 (BOTTOM)

WATER SURFACE AREA = 22,820 SF

OUTLET STRUCTURE  
 2 BAY (GRADED)  
 INLET WALL (TOP=685.5)  
 4" H X 21" W NOTCH INV=685.1  
 LOWER BAY WALL (TOP=686.7)  
 3 1/2" ORIFICE ● 685.1  
 TOP WALL ● 688.0  
 OUTLET 15" RCP ● 685.0



APR./2013

5017 GREEN BAY ROAD  
 SUITE 126  
 KENOSHA, WI 53144  
 PHONE : 262.657.1550  
 FAX : 262.657.1594

**Clark Dietz**  
 ENGINEERS

K0300080

**Ponds Owned and Maintained  
By Private Owner  
Woodmans Basin A**



July 11, 2013

### Measurement Results for Woodmans Basin A Pond



Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1995	4	4.8 – 5.9	2018

### Notes


1. The designed water depth of the pond is approximately 4 feet; the design plans are not clear. The measured water depth in Spring of 2013 varied between 4.8 and 5.9 feet.
2. The inlet and outlet pipes were inspected and were found to be in good structural condition.
3. Sediment build-up varied between 0 and 0.8 feet.
4. The outlet was plugged with dirt and vegetation.
5. There is moderate willow and cattails growth around the majority of the pond, including the inlet and outlet structures.
6. The pond contains muskrats and showed signs of past beaver activity.
7. Trash is scattered all around the pond area.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. The pond should be dredged at the south end and near the outlet structures.
3. The vegetation should be cleared, especially around the structures.
4. Routine mowing and clean-up should be performed.











# WOODMANS BASIN A

WATER ELEV.  
687.1


DEPTHS BELOW WATER



0.0 (TOP SEDIMENT)  
0.0 (BOTTOM)

1.0  
2.5

WATER SURFACE AREA = 84,521 SF





**Clark Dietz**  
ENGINEERS

APR./2013

K0300080

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

Ponds Owned and Maintained  
By Private Owner  
Indian Trail Estates-YMCA



July 11, 2013

### Measurement Results for Indian Trail Estates/YMCA Pond


Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2001	4' – 8'	4.2 – 6.7	2018


### Notes


1. The designed water depth of the pond is 4 feet at the east end and 8 feet at the west end. The measured water depth in July of 2013 varied between 4.2 and 6.7 feet. We conclude that sediment is starting to build up in this pond.
2. The inlet and outlet pipes were inspected and were found to be in good structural condition. Some rip-rap areas have been washed out.
3. Sediment build-up varied between 0.6 and 1.2 feet.
4. There is thick vegetation growing around the perimeter of the pond, including in the rip-rap areas near the inlet and outlet structures.
5. Pond scum covered the entire pond during the July inspection.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. The vegetation within and surrounding the inlet and outlet structures should be cleared.
3. When mowing, leave a grassy strip around the perimeter of the pond to deter geese and improve safety.
4. The washed-out rip-rap areas should be repaired.
















# INDIAN TRAILS – YMCA

DEPTHS BELOW WATER

WATER ELEV.  
679.6


0.0 (TOP SEDIMENT)  
0.0 (BOTTOM)

WATER SURFACE AREA = 34,334 SF



**OUTLET STRUCTURE**  
2.5'X5.5' INV. @ 679.6  
8.5" Ø ORIFICE @ 679.4  
TOP WALL @ 682.3  
OUTLET PIPE = 18" RCP  
15.5" Ø ORIFICE @ 679.3

*52ND ST*





**Clark Dietz**  
ENGINEERS

FEB./2013

KO300080

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

Ponds Owned and Maintained  
By Private Owner  
Leona' s Rolling Meadows  
Subdivision C1



September 18, 2013

**Measurement Results for Leona's Rolling Meadows Subdivision C1 Pond**

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2003	6	4.5 – 6.0	2018


**Notes**

1. The designed water depth of the pond is 6 feet. The measured water depth in July of 2013 varied between 4.5 and 6.0 feet. We conclude that the pond was over-excavated at the time of construction but is now filling with sediment.
2. The inlet bells have some small chips. The outlet structure is in good condition.
3. Sediment build-up averages about 0.7 feet.
4. The whole pond perimeter is mowed. The rip-rap areas have a small amount of vegetation growing in them but are in good condition.
5. There is a growth of cattails in one end of the pond.

**RECOMMENDATIONS**

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. Rip-rap should be kept free of vegetation.
3. The cattails should be cleared if they continue to extend into the pond.
4. A narrow strip around the pond should be left un-mowed to deter geese.
5. The pond should be dredged and restored to its design depth.











4-2-13 Sunday 35°  
AT, BB

LEONAS MEADOWS BASIN # C1


± 9290 Elev 9319

\* DEPTH S

MAINTENANCE

- Small near cattails
- Beck chipmunk ZIF.E.S.

7-1-13  
 9320 - 5.0, 6.4  
 6.2, 6.7  
 4.7, 5.4  
 9323 5.0, 6.5  
 4.5, 4.7 } were RL



**LEONAS ROLLING MEADOWS – BASIN C1**


WATER ELEV.= 682.0

DEPTHS BELOW WATER

5.4 (TOP SEDIMENT)

6.0 (BOTTOM)

WATER SURFACE AREA = 35,933 SF



**Clark Dietz**  
ENGINEERS

FEB./2013

K0300080

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

Ponds Owned and Maintained  
By Private Owner  
Leonas Rolling Meadows  
Subdivision C



July 10, 2013

### Measurement Results for Leona's Rolling Meadows Subdivision C Pond


Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2003	7	4.1 – 7.8	2018

### Notes

1. The designed water depth of the pond is 7 feet. The measured water depth in April of 2013 varied between 4.1 and 7.8 feet. The pond was likely over-excavated at the time of construction but is now starting to fill up with sediment.
2. Pond scum was blocking the outlet grate.
3. Sediment build-up varied between 0.1 and 0.9 feet.
4. The entire pond perimeter area has been mowed to the water's edge.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. The outlet grate should be cleaned periodically.
3. A strip of grass should be left around the edge of the pond to improve safety and help to prevent geese.
4. Perform dredging at the pond and excavate to the design depth.








4-2-3 SUMY 350  
AT, B/B


LEON'S POND WINDMILL  
BASIN # C

STAGE # 8800

- \* LIGHT GRATE CLEANING PERIODICALLY
- \* POND SUMY BLOCK IN GRATE
- E/W DEPTHS
- ORIFICES?



\* RIVER OTTED STBLG 7-1-13  
TRACKS IN MARCH ON ICE



7-1-13	9003	74,8.3	64,6.9	75,8.2	59,6.3	72,2.5	74,7.7	78,8.0	74,7.9
9003	41,1.2	70,7.8							



Ponds Owned and Maintained  
By Private Owner  
KM Property Owners  
South Port Plaza B



July 16, 2013

### Measurement Results for South Port Plaza Basin B – West Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1993	N/A	1.5 – 3.9	2018


### Notes

1. The designed water depth of the pond is unknown; the plans show that the outlet elevation is the same as the pond bottom. The pond holds water, so this is not accurate. The measured water depth in July of 2013 varied between 1.5 and 3.9 feet.
2. The inlet and outlet pipes were inspected and were found to be in good structural condition. The lower outlet chamber was full of mud, indicating that the lower orifice might be blocked.
3. Sediment build-up ranged between 0.5 and 2.4 feet.
4. The entire pond perimeter is mowed.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. Further investigations are needed to determine the design depth.
3. Sediment is deep in some areas and dredging may be necessary.
4. The outlet structure should be cleaned and inspected for obstructions.
5. When mowing, leave a grassy strip around the edge of the pond to deter geese.










**SOUTHPORT PLAZA BASIN B**

WATER ELEV.  
687.6


DEPTHS BELOW WATER

0.0 (TOP SEDIMENT)  
⊕  
0.0 (BOTTOM)


WATER SURFACE AREA = 11,682 SF



OUTLET STRUCTURE  
LOWER GRATED OPENING  
I.E. ⊕ 685.6  
2'x4' GRATED OPENING  
IN-SPILL ⊕ 687.6  
10" D.I.P. OUTLET ⊕ 685.5



OUTLET STRUCTURE



MAY/2013

**Clark Dietz** ENGINEERS K0300080

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

Ponds Owned and Maintained  
By Private Owner  
Mahone



July 11, 2013

### Measurement Results for Mahone Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2012 – Rehab	N/A	3.0 – 5.2	2018

### Notes

1. The designed water depth of the pond is unknown; the pond rehabilitation plans do not show a bottom elevation. The measured water depth in July of 2013 varied between 3.0 and 5.2 feet.
2. The inlet and outlet pipes were inspected and were found to be in good structural condition.
3. Sediment build-up ranged between 0 and 1.1 feet.
4. Weed growth is thick at the north end of the pond. Some rip-rap areas have vegetation growing in them. Vegetation has grown up around the majority of the pond perimeter, including near the inlets and outlets.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. Tree and shrub clearing is necessary at the inlets and outlets.
3. Weeds at the north end of the pond should be cleared.
4. The pond area should be mowed and cleared regularly.
5. Further investigation is necessary to determine the design depth of the pond, and whether dredging may be needed.













4-2-2013

Sunny, 40°

AT, BB

NAHPNE - INDIAN TRAIL ACADEMY

START # 9900

END # 10079

\* NON-MOWED EDGES

\* NEEDS SOME TREE CLEARING @ EAST


15" F.E.S

\* NEEDS LIGHT SCRUB CLEARING @ INTAKE

AND CONC. OVERFLOW


\* NEED BOTTOM DEPTHS

CLEAR WITH  
-TRAIL WEEDS WORTH AND



TWO 8.75" DEPTHS  
(WEED)  
-1.5 (PUMP)

↑ N



77.55
10,080-512
-41,512
47,523
361
30,314
4.5
43,418
3.0
40,412
10,080


**MAHONE**

WATER ELEV.  
690.0

**DEPTHS BELOW WATER**

0.0 (TOP SEDIMENT)  
◆  
0.0 (BOTTOM)

WATER SURFACE AREA = 252,654 SF



Ponds Owned and Maintained  
By Private Owner  
Dairyland Greyhound Park  
West



January 16, 2014

### Measurement Results for Dairyland West Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
N/A	N/A	3.3	2018

### Notes


1. The original pond design plans were not available. The measured water depth in February of 2013 was 3.3 feet.
2. No inlet and outlet pipes were located during the pond inspection.
3. Sediment build-up was 0.8 feet.
4. The whole pond perimeter area is heavily vegetated with cattails and other plants.
5. There is no defined top edge of the pond.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. Clearing of the cattails and vegetation is necessary to locate the inlet and outlet structures.



DAIRYLAND ROAD (W)





- \* NO VISIBLE PIPES
- \* NATURAL LOW AREA?
- 196-1974 FLDI = 4.5
- \* NO DEFINED "EDGE" OR "TOP"
- \* CATCHAL PERIMETER
- HI QUALITY WETLANDS

DAIRYLAND WEST

DEPTHS BELOW WATER

- ◆ 0.0 (TOP SEDIMENT)
- ◆ 0.0 (BOTTOM)

WATER SURFACE AREA = 182,000 SF



	FEB./2013	5017 GREEN BAY ROAD
	K0300080	SUITE 126
		KENOSHA, WI 53144
		PHONE : 262.657.1550
		FAX : 262.657.1594

Ponds Owned and Maintained  
By Private Owner  
Dairyland Greyhound Park  
North



January 16, 2014

### Measurement Results for Dairyland West Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
N/A	N/A	3.3	2018

### Notes


1. The original pond design plans were not available. The measured water depth in February of 2013 was 3.3 feet.
2. No inlet and outlet pipes were located during the pond inspection.
3. Sediment build-up was 0.8 feet.
4. The whole pond perimeter area is heavily vegetated with cattails and other plants.
5. There is no defined top edge of the pond.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. Clearing of the cattails and vegetation is necessary to locate the inlet and outlet structures.



DAIRYLAND ROAD (W)





- \* NO VISIBLE PIPES
- \* NATURAL LOW AREA?
- 196-1974 FLDI = 4.5
- \* NO DEFINED "EDGE" OR "TOP"
- \* CATCHAL PERIMETER
- HI QUALITY WETLANDS

DAIRYLAND WEST

DEPTHS BELOW WATER

- ◆ 0.0 (TOP SEDIMENT)
- ◆ 0.0 (BOTTOM)

WATER SURFACE AREA = 182,000 SF



	FEB./2013	5017 GREEN BAY ROAD
	K0300080	SUITE 126
		KENOSHA, WI 53144
		PHONE : 262.657.1550
		FAX : 262.657.1594

**LOW PRIORITY  
MAINTENANCE REQUIREMENTS**

**2014 KENOSHA POND MAINTENANCE REQUIREMENTS  
PRIVATELY OWNED WITH MAINTENANCE AGREEMENT**

#	POND NAME	3 acres or more?	WET/ DRY	DREDGING?	INLET/OUTLET IMPROVEMENTS?	VEGETATION REMOVAL?	REHABILITATION NEEDED	ESTIMATED COST	ENGINEERING & ADMINISTRATION	CONTINGENCIES	TOTAL COST FOR EACH POND	WORK PRIORITY	PRIORITY RANKING	TOTAL COST OF PROJECTS BY PRIORITY	YEARS TO COMPLETION WITH \$100,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$200,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$300,000 ANNUAL BUDGET <sup>1</sup>
16	Peterson's Golden Meadow A		Wet		Yes		Stabilize erosion near outlet structure and clean lower outlet.	\$5,000	\$600	\$840	\$6,440	Low	1	\$43,792	4.4	2.2	1.5
48	Regal Apartments		Wet		Yes	Yes	Repair end section on 18" pipe.	\$1,000	\$480	\$672	\$5,152	Low	2				
							Remove vegetation at structures and spillway.	\$2,000									
							Mow area around pond.	\$1,000									
7	Kenosha Trade Commerce		Wet		Yes		Reattach end section on 27" inlet.	\$1,000	\$120	\$168	\$1,288	Low	4				
54	Heritage Heights 1A		Wet			Yes	Clear vegetation from structures.	\$2,000	\$840	\$1,176	\$9,016	Low	6				
							Remove cattails from pond interior.	\$5,000									
55	Heritage Heights 1B		Wet			Yes	Clear vegetation from structures.	\$2,000	\$840	\$1,176	\$9,016	Low	7				
							Remove cattails from pond interior.	\$5,000									
19	North Point Subd. Prayer House of God		Wet			Yes	Remove vegetation from rip-rap and structures.	\$2,000	\$240	\$336	\$2,576	Low	9				
17	Peterson's Golden Meadow B1		Wet				Clear debris from grates.	\$1,000	\$120	\$168	\$1,288	Low	10				
28	Shagbark	Yes	Wet			Yes	Clear vegetation from inlet structure.	\$1,000	\$120	\$168	\$1,288	Low	13				
8	Kenosha Bible Church		Wet			Yes	Remove vegetation around perimeter and outlet structure.	\$2,000	\$240	\$336	\$2,576	Low	15				
13	Leona's Rolling Meadows Subdivision F		Wet			Yes	Remove vegetation from rip-rap.	\$2,000	\$240	\$336	\$2,576	Low	16				
4	Dairyland Greyhound Park (SOUTH)		Wet			Yes	Remove perimeter vegetation.	\$2,000	\$240	\$336	\$2,576	Low	17				

NOTES:  
1. Assumes 50% of budget to high-priority projects, 40% to medium-priority projects, and 10% to low-priority projects.

Ponds Owned and Maintained  
By Private Owner  
Peterson' s Golden Meadow  
A



July 10, 2013

### Measurement Results for Petersons Golden Meadow A Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2003	5	5.4	2018

### Notes

1. The designed water depth of the pond is 5 feet. The measured water depth in March of 2013 was 5.4 feet. We conclude that the pond was over-excavated at the time of construction.
2. The inlet and outlet pipes were inspected and were found to be in good structural condition. The grate on the 24" pipe was clogged with leaves.
3. Sediment build-up varied between 0 and 0.5 feet.
4. The whole pond perimeter area is mowed.
5. There is some erosion near the outlet structure.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. Clean out the lower outlet and the surrounding area.
3. When mowing, leave a strip of grass around the pond to improve safety and help to prevent geese.
4. Repair and stabilize the erosion near the outlet structure.





3-24-13 Sunny 48°

AT, BF  
 PERSON BASIN A

# 850D →  
 870B BW

\* ~~REPAIR~~ E/O & DEFINT ✓

\* PUMP IN GOOD SHAPE  
 \* LIGHT MAINTENANCE

- CLEAN OUT LOWER OUTLET  
 & SURROUNDING AREA

24' GRATE CLOSED w/ LEAVES


7-4-13 TWTR  
 870B - S, S, 6, 2  
 SH, -  
 SIB, S, 6  
 S, 2, S, 4  
 S, 6, 7 -  
 S, 6, 10 -  
 SIB, S, 5

52<sup>nd</sup> ST

T  
 CWO ED

P.P

4.3



# PETERSONS GOLDEN MEADOWS BASIN A

WATER ELEV.= 707.1


DEPTHS BELOW WATER

◆ 0.0 (TOP SEDIMENT)

◆ 0.0 (BOTTOM)

WATER SURFACE AREA = 41,619 SF

60TH ST.



FEB./2013

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

**Clark Dietz**  
ENGINEERS

K0300080

Ponds Owned and Maintained  
By Private Owner  
Regal Apartments



September 5, 2013

### Measurement Results for Regal Apartments Pond


Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2002	3	4.7 – 5.2	2018


### Notes

1. The designed water depth of the pond is approximately 3 feet; the design plans are not clear. The measured water depth in June of 2013 varied between 4.7 and 5.2 feet. The pond was possibly over-excavated at the time of construction.
2. The inlet and outlet structures were inspected. The end section of the 18" pipe is separated.
3. Sediment build-up varied between 0.2 and 0.5 feet.
4. The pond perimeter and spillway had not been mowed. Buckthorn is growing at the southeast corner. Vegetation is growing in the inlet and outlet structures

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. The buckthorn and vegetation at the inlet and outlet structures should be removed.
3. The pond perimeter should be mowed to within a foot of the water.
4. The spillway should also be mowed.







6/13/13 AT Sunny → S

REBEL APT'S

STREET 15100 → 151210  
(RENUMBER) 145100 → 145147


RESTRICT 15300 ↑

MAINTENANCE

- \* mow & clear out BUCKETHEADS SIDE COURTYARD
- \* mow - DRIVEWAY
- \* REPAIR SECTION OF 18" SEPERATED.
- \* \_\_\_\_\_

7-2-13	3005	-	50	5.2
			49	-
			52	-
			47	5.2

4, 5<sup>2</sup>



↑

REGAL APTS


WATER ELEV.=688.2

DEPTHS BELOW WATER


5.0 (TOP SEDIMENT)

5.2 (BOTTOM)

WATER SURFACE AREA = 1,271,593 SF



OUTLET STRUCTURE



JUNE/2013

K0300080

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

**Ponds Owned and Maintained  
By Private Owner  
Kenosha Trade Commerce**



October 3, 2013

### Measurement Results for Kenosha Trade Commerce Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2002	5.5	5.4	2018

### Notes

1. The designed water depth of the pond is 5.5 feet. The measured water depth in July of 2013 was approximately 5.4 feet. We conclude that the pond was over-excavated at the time of construction.
2. The inlet and outlet pipes were inspected and were found to be in good condition. The end section on the 27" inlet pipe on the south side of the pond was separated from the pipe.
3. Sediment build-up varied between 0.1 and 0.6 feet.
4. The whole pond perimeter is mowed. The entire pond area is in good condition.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. Consider not mowing a one-foot strip around the pond in order to deter geese.







4-4-13  
AT GB



KENASAA TRADE + COMMERCE

START # 10700  
END # 10795

MAINT.  
HEALTHY POUD  
SEPARATED 27 (SOUTH SIDE)

10795 - 5.4, 16.0 7-7-13  
1916 5.6, 16.0  
97 5.3, 5.5  
10798 5.4, 5.5

INTAKE STRUCTURE



# KENOSHA TRADE COMMERCE


WATER ELEV.  
683.7

DEPTHS BELOW WATER

5.4 (TOP SEDIMENT)

5.8 (BOTTOM)

WATER SURFACE AREA = 15,585 SF



FEB./2013

**Clark Dietz**  
ENGINEERS

K0300080

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

Ponds Owned and Maintained  
By Private Owner  
Heritage Heights 1A



October 30, 2013

### Measurement Results for Heritage Heights 1A Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2005	4	3.0 – 3.7	2018

### Notes

1. The designed water depth of the pond is 4 feet. The measured water depth in October of 2013 varied between 3.0 and 3.7 feet.
2. The inlet and outlet structures were inspected and are in good condition.
3. Sediment build-up varied between 0.5 and 1.3 feet.
4. The pond perimeter had been mowed.
5. Vegetation is growing within the inlet and outlet structures.
6. There is thick cattail growth all around the pond.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.  
?- Sediment has already built up within the pond and dredging should be considered.
2. The cattails around the interior perimeter of the pond should be removed.
3. The pond perimeter should be mowed to within a foot of the water.
4. The inlet and outlet structures should be kept clear of vegetation.








1/4 ... SUM ... BRG  
 STAMP ... CR + W # 1A  
 SMDK: 21300  
 HERITAGE HTS - 1A  
 MX ...  
 TRM CAT-TAILS @ ... N ... STR.  
 AND 30' F.E.S  
 BOTTOM SHOTS: 21482 - 21443

SHOTS 21415 - 21420  
 - GRASS OUTSIDE FLOORS + MO  
 FLOWMETERS

SHOT	TOP SLT	BOT SLT
21433	3.2	4.4
21434	3.5	4.55
21435	3.2	4.75
21436	3.6	4.80
21437	3.7	4.30
21438	3.60	4.35
21439	3.6	4.85
21440	3.00	4.05
21441	3.15	3.65
21442	3.7	4.05
21443	3.7	4.50



# HERITAGE HEIGHTS - 1A

WATER ELEV.= 730.1


DEPTHS BELOW WATER

3.5 (TOP SEDIMENT)



4.4 (BOTTOM)

WATER SURFACE AREA = 11,000 SF



OCT./2013

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

**Clark Dietz**  
ENGINEERS

K0300080

**Ponds Owned and Maintained  
By Private Owner  
Heritage Heights 1B**



October 30, 2013

**Measurement Results for Heritage Heights 1B Pond**

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2005	4	2.0 – 3.8	2018

**Notes**

1. The designed water depth of the pond is 4 feet. The measured water depth in October of 2013 varied between 2.0 at the north end of the pond and 3.8 feet at the south end. The pond has apparently begun to fill up with sediment.
2. The inlet and outlet structures were inspected and are in good condition. There is thick vegetation growth at the structures and within the surrounding riprap.
3. Sediment build-up varied between 0.1 and 2.4 feet.
4. The pond perimeter had been mowed. There is thick cattail growth throughout the pond.

**RECOMMENDATIONS**

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal. Dredging should be considered within the next five years due to the sediment buildup that has already occurred in the pond.
2. The vegetation at the inlet and outlet structures should be removed and kept clear of future growth.
3. The pond perimeter should be mowed to within a foot of the water.
4. The cattails throughout the pond should be cleared.






strawberry

HERITAGE HTS # 10

shots ~~21230~~ 21000 -

POND BOTTOM: 21231 - 2126 21230

SHOT	TOP SHT	BOT SHT
21232	2.0	4.35
21233	2.05	3.65
21234	2.05	2.65
21235	2.35	3.90
21236	2.30	3.35
		21237 2.60 2.80
		21238 3.80 4.30
		21239 3.05 4.10
		21240 3.05 3.20
		21241 2.65 3.90
		21242 3.35 4.25



# HERITAGE HEIGHTS - 1B


WATER ELEV. = 734.6

DEPTHS BELOW WATER

2.7 (TOP SEDIMENT)

3.7 (BOTTOM)

WATER SURFACE AREA = 13,012 SQ FT



OCT./2013

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

**Clark Dietz**  
ENGINEERS  
K0300080

**Ponds Owned and Maintained  
By Private Owner  
Heritage Heights 1B**

**Ponds Owned and Maintained  
By Private Owner  
North Point Subdivision  
Prayer House of God**



September 5, 2013

### Measurement Results for North Pointe Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2001	6	6.1 – 7.2	2018

### Notes

1. The designed water depth of the pond is 6 feet. The measured water depth in July of 2013 varied between 6.1 and 7.2 feet. We conclude that the pond was over-excavated at the time of construction.
2. The inlet and outlet pipes were inspected and were found to be in good condition. Brush is growing in some of the structures.
3. Sediment build-up varied between 0.5 and 0.9 feet.
4. The whole pond perimeter was mowed. Some rip-rap areas had vegetation growing in them.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. Brush and saplings should be removed from the inlet and outlet structures and the other areas where growth is heaviest.







# NORTH POINTE



WATER ELEV.=610.1

DEPTHS BELOW WATER

6.7 (TOP SEDIMENT)

7.4 (BOTTOM)

WATER SURFACE AREA = 237,590 SF





**Clark Dietz**  
ENGINEERS

JUNE/2013

K0300080

5017 GREEN BAY ROAD  
 SUITE 126  
 KENOSHA, WI 53144  
 PHONE : 262.657.1550  
 FAX : 262.657.1594

Ponds Owned and Maintained  
By Private Owner  
Peterson' s Golden Meadow  
B1



July 10, 2013

**Measurement Results for Petersons Golden Meadow B1 Pond**

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2003	5	4.6 – 5.3	2018

**Notes**

1. The designed water depth of the pond is 5 feet. The measured water depth in February of 2013 varied between 4.6 and 5.3 feet. We conclude that the pond was over-excavated at the time of construction and is be starting to fill with sediment in certain areas.
2. The inlet and outlet pipes were inspected and were found to be in good structural condition.
3. Sediment build-up varies between 0.5 to 0.8 feet.
4. The whole pond perimeter area is mowed.

**RECOMMENDATIONS**

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. When mowing, leave a strip of grass around the pond perimeter to improve safety and help to deter geese.
3. Keep grates free of debris.










23

2/26/13 AT BS Quay 31' Windy

**PERSON'S GROUND: MIDDLE BASIN 1**


46300

SQUARE INTAKE STRUCTURE DETAIL



7-1-13  
 8084 - 5.3, 6.1  
 87 4.8, 5.6  
 88 4.6, 5.3  
 89 5.0, 5.5  
 90 4.9, 5.4  
 8089 4.8, 5.3  
 EW 70 8.15

- NO MAINT. REQ'D ?
  - NO OVERFLOW ?
- NEED:** - ~~DEPTH~~  
 - DEPTHS





# PETERSONS GOLDEN MEADOWS BASIN B1

WATER ELEV.= 701.2

DEPTHS BELOW WATER

- ◆ 0.0 (TOP SEDIMENT)
- ◆ 0.0 (BOTTOM)

WATER SURFACE AREA = 41,656 SF



**OUTLET STRUCTURE**  
 4'x4' LOWER GRATED OPENING  
 LOWER PLATED 12" RCP W/6.5" ORIFICE @ 701.0  
 5'x4' UPPER GRATED OPENING  
 IN-SPILL OF UPPER @ 702.9  
 OUTLET 15" RCP @ 701.0

NO EMERGENCY SPILLWAY OVERFLOW

FEB./2013

5017 GREEN BAY ROAD  
 SUITE 126  
 KENOSHA, WI 53144  
 PHONE : 262.657.1550  
 FAX : 262.657.1594

**Clark Dietz**  
 ENGINEERS K0300080

Ponds Owned and Maintained  
By Private Owner  
Shagbark



January 16, 2014

### Measurement Results for Shagbark Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2005	4	3.8 – 4.3	2018

### Notes

1. The designed water depth of the pond is 4 feet. The measured water depth in July of 2013 varied between 3.8 and 4.3 feet.
2. The inlet and outlet structures were in good condition.
3. No sediment build-up was found in the pond.
4. The pond area had been mowed.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. Keep the inlet structure clear of vegetation.





6-26-3

8. 1902X 12-1A098



~~FL~~ Taken 8/22

7:3-13	T/V	-
39275	4.1	-
	4.0	-
	4.3	-
	4.1	-
	3.8	-
39780	4.2	-
	4.0	-


- \* TOE/EW
- \* WTR SHOT
- \* STRUCTURE SECTIONS

Concrete gullyway base flat bottom (concl/cons)  
 All Ew1 are also TOE, except NE corner

↑ Note TOP / PLAN VIEW



- ① 3 GATES 5' x 5' etc.
- ② 2 GATES 5' x 5' etc.




SHAGBARK  
 WATER ELEV.= 632.7  
 DEPTHS BELOW WATER

4.1 (TOP SEDIMENT)


◆ (BOTTOM)

WATER SURFACE AREA = 211,815 SF



LOWER STRUCTURE

OUTLET STRUCTURE



JUNE/2013

5017 GREEN BAY ROAD  
 SUITE 126  
 KENOSHA, WI 53144  
 PHONE : 262.657.1550  
 FAX : 262.657.1594

**Clark Dietz**  
 ENGINEERS K0300080

**Ponds Owned and Maintained  
By Private Owner  
Kenosha Bible Church**



July 16, 2013

### Measurement Results for Kenosha Bible Church Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
1997	3.5	2.7 – 4.0	2018

### Notes

1. The designed water depth of the pond is 3.5 feet. The measured water depth in May of 2013 varied between 2.7 and 4.0 feet. The pond was likely over-excavated at the time of construction but is now starting to fill with sediment.
2. The inlet and outlet pipes were inspected and were found to be in good structural condition.
3. Sediment build-up ranged between 0 and 0.4 feet.
4. The whole pond perimeter is mowed. There is thick cattail growth on the east and west sides of the pond, including around the outlet.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. Clear cattails from the pond, especially around the outlet structure.
3. When mowing, leave a grassy strip around the pond to deter geese and improve safety.





5-23-73 AT 416 CLOUDY 50°


START  
13300 → 13423

KEMOS BISE CINECT

MAINTENANCE

- \* KEEP WIRE CLEAN
- (CONTAINS INSURABLE)
- \* POSSIBLE CONTACT REMOVAL
- \* LEAD SHAP

13425	2.7, 2.9
	3.9, 3.9
	4.0, 4.0
	3.1, 3.1



# KENOSHA BIBLE CHURCH


WATER ELEV.= 696.7

DEPTHS BELOW WATER


0.0 (TOP SEDIMENT)

0.0 (BOTTOM)

WATER SURFACE AREA = 27,123 SF



OUTLET STRUCTURE





**Clark Dietz**  
ENGINEERS

MAY./2013

K0300080

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

Ponds Owned and Maintained  
By Private Owner  
Leona's Rolling Meadows  
Subdivision F



July 10, 2013

**Measurement Results for Leona's Rolling Meadows Subdivision F Pond**

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2003	6	5.7 – 7.0	2018

**Notes**


1. The designed water depth of the pond is 6 feet. The measured water depth in April of 2013 varied between 5.7 and 7.0 feet. We conclude that the pond was over-excavated at the time of construction.
2. The inlet and outlet pipes were inspected and were found to be in good structural condition.
3. The outfall RCP is higher than the orifice.
4. Sediment build-up averaged 0.25 feet.
5. The whole pond perimeter is mowed. Rip-rap areas have vegetation growing in them.

**RECOMMENDATIONS**

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. The brush growing in the rip-rap around the structures should be cleared.
3. A strip of grass should be left around the edge of the pond to improve safety and help to prevent geese.



0











4-2-13 Sunny 35°  
AST, BB


LEDNA'S MEADOWS BASIN F



- \* NEED LIGHT CLEARING @ 30" FES
- \* NEED POND BOTTOM DEPTHS
- NOTE: OUTFALL RUP MUST BE 0.15-0.20' HIGHER THAN ORIFICE.



3.5" ORIFICE WEIR PLATE  
-1.1



HIGHER THAN ORIFICE


# LEONAS ROLLING MEADOWS – BASIN F

WATER ELEV.  
679.9

## DEPTHS BELOW WATER

0.0 (TOP SEDIMENT)  
◆  
0.0 (BOTTOM)

WATER SURFACE AREA = 9,182 SF





**Clark Dietz**  
ENGINEERS

FEB./2013

K0300080

5017 GREEN BAY ROAD  
SUITE 126  
KENOSHA, WI 53144  
PHONE : 262.657.1550  
FAX : 262.657.1594

Ponds Owned and Maintained  
By Private Owner  
Leona's Rolling Meadows  
Subdivision F

Ponds Owned and Maintained  
By Private Owner  
Dairyland Greyhound Park  
South



January 16, 2014

### Measurement Results for Dairyland South Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
N/A	N/A	3.4 – 4.2	2018

### Notes

1. The original pond design plans were not available. The measured water depth in February of 2013 varied between 3.4 and 4.2 feet.
2. The inlet and outlet pipes were inspected and were found to be in good structural condition. The pipe joints are also in good condition.
3. Sediment build-up varied between 0 and 0.8 feet.
4. Vegetation has grown up around the entire pond perimeter; some areas are thick with willow brush.
5. There was a layer of duckweed on the pond in June 2013.

### RECOMMENDATIONS


1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. Some willow brush and other vegetation should be cleared around the pond perimeter.











27613 15° Sway

DAIRYLAND SOUTH

10' LOT  
RIPPER  
COPS

PARKING LOT

PIPE DOWN STAKE

SHOT AND TEST (CAP 6\"/>

5' HOLE

(FROM N. ROAD)  
LINES  
PLANT W/ED  
(S & A/CANT)

\* AREAS OF  
THICK WILLOW

DEPTH

- 1709 - 3.2,
- 10 - 3.4, 4.0
- 11 - 3.5, 4.3
- 12 - 3.7, 4.6
- 13 - 3.7, 4.4

4.2, 4.6

(W/ED T.L.S FROM  
100' SURFACE)

PIPE DOWN STAKE  
OK

(9)

GRANTE

1.10

20' HOLE  
REBAR  
OUT.

30' HOLE

4.1

12' HOLE

6 BAYS




DAIRYLAND SOUTH

DEPTHS BELOW WATER

0.0 (TOP SEDIMENT)

⊕ 0.0 (BOTTOM)

WATER SURFACE AREA = 96,000 SF




**Clark Dietz**  
 ENGINEERS

FEB./2013  
 5017 GREEN BAY ROAD  
 SUITE 126  
 KENOSHA, WI 53144  
 PHONE : 262.657.1550  
 FAX : 262.657.1594

K0300080

**NO MAINTENANCE REQUIREMENTS**

**2014 KENOSHA POND MAINTENANCE REQUIREMENTS  
PRIVATELY OWNED WITH MAINTENANCE AGREEMENT**

#	POND NAME	3 acres or more?	WET/ DRY	DREDGING?	INLET/OUTLET IMPROVEMENTS?	VEGETATION REMOVAL?	REHABILITATION NEEDED	ESTIMATED COST	ENGINEERING & ADMINISTRATION	CONTINGENCIES	TOTAL COST FOR EACH POND	WORK PRIORITY	PRIORITY RANKING	TOTAL COST OF PROJECTS BY PRIORITY	YEARS TO COMPLETION WITH \$100,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$200,000 ANNUAL BUDGET <sup>1</sup>	YEARS TO COMPLETION WITH \$300,000 ANNUAL BUDGET <sup>1</sup>
18	Peterson's Golden Meadow B2		Wet				None.				N/A						

NOTES:

1. Assumes 50% of budget to high-priority projects, 40% to medium-priority projects, and 10% to low-priority projects.

Ponds Owned and Maintained  
By Private Owner  
Peterson' s Golden Meadow  
B2



July 10, 2013

### Measurement Results for Petersons Golden Meadow B2 Pond

Year Constructed	Design Water Depth	Measured Water Depth	Next Recommended Water Depth Measurement
2003	5	5.0 – 5.9	2018

### Notes

1. The designed water depth of the pond is 5 feet. The measured water depth in February of 2013 varied between 5.0 and 5.9 feet. We conclude that the pond was over-excavated at the time of construction.
2. The inlet and outlet pipes were inspected and were found to be in good structural condition.
3. Sediment build-up varies between 0 and 0.4 feet.
4. The whole pond perimeter is mowed.
5. The pond is in like-new condition.

### RECOMMENDATIONS

1. The water depth should be measured in 2018 to compare to the 2013 measurements. This will provide a comparable depth to determine the rate of sediment accumulation as well as an anticipated date for sediment removal.
2. When mowing, leave a strip of grass around the pond perimeter to improve safety and deter geese.





2/26/73 AT, B.B. 31° Cloudy, windy

PETERSONS BOWEN MEADOW BASIN 2

# 6,200 - 6112 / 6113 FWI →


~~DETER~~ 5110

NEED - FILLIE WATER  
- DEPTHS

- OUTLET ? (EQUILIZATION P DET B)  
- OVER FLOW ? NO

7-1-13
6134 - 5147
5.2, 5.4
5.4, 5.4
5.0, 5.4
5.3, 5.5
5.4, 5.7
5.5, -
5.7, -
5.9, -
6142

36' EXP  
(TO RAIN #1)



NEW CONDITION  
- NO MAINTENANCE NEEDED

